



Date: 12 October 2007

IMPORTANT SAFETY NOTICE

Dear John Deere Customer:

In voluntary cooperation with the U.S. Consumer Product Safety Commission (CPSC), Deere & Company is recalling certain John Deere XUV and HPX Utility Vehicles. Our records show that you own one of these affected Utility Vehicles.

PROBLEM: An incorrect brake caliper may have been installed on the front of the vehicle. An incorrect caliper may cause improper braking resulting in the vehicle pulling to one side during hard braking.

PRODUCT: John Deere XUV and HPX Utility Vehicles with the following model and serial number ranges.

Model	Serial Number Ranges
XUV 620i Gas (Green)	M0XUVGX013294 thru M0XUVGX016669
XUV 620i Gas (Olive)	M0XUVGT011480 thru M0XUVGT012186
XUV 850D Diesel (Green)	M0XUVDX011917 thru M0XUVDX013329
XUV 850D Diesel (Olive)	M0XUVDT010001 thru M0XUVDT010449
HPX 4X4 Diesel	M0HP4DX050877 thru M0HP4DX051453
HPX 4X4 Gas	M0HP4GX051221 thru M0HP4GX052763

WHAT TO DO:

Please contact your nearest John Deere dealer to schedule an appointment to have the calipers inspected. If the dealer does find any incorrect caliper installed, he will correct the installation. This update will be performed at no cost to you.

Until this inspection is performed, please be aware that in a hard braking situation, the vehicle may have a tendency to pull to one side. Slow down before braking whenever possible to avoid hard braking situations.

If you no longer own the Utility Vehicle please take a few moments to complete and mail the enclosed postage paid reply card.

We hope this recall will not cause you any undue inconvenience. Our efforts are intended to ensure your continued satisfaction with John Deere products and safe operation of your Utility Vehicle.

If you have any questions, please contact the Customer Contact Center at **1-800-537-8233**.

Sincerely,

*John Deere Worldwide Commercial and Consumer Equipment Division
John Deere Horicon Works*