

AutoTrac™ Controller 300

Software Update 20-2 Release Notes
3.23 J



JOHN DEERE

Resolved Items

Automation Time-out Issues with Line Acquires

Previous software allowed Automation Timeout to occur when unable to achieve line acquires in a period of time. This was most common on articulated tractors, as well as machines with cold hydraulic oil (<68 deg F). This release fixes this issue by allowing the AutoTrac™ Controller 300 motor to turn for a longer period of time before disengaging with “Automation Timeout”.

Release Notice

These are software release notes for the AutoTrac™ Controller 300. Release Notes can be found on www.stellarsupport.com. Note: Your use of the software is governed by the End User License Agreement included with the software.