StarFire[™] 3000 Receiver

Software Update 20-2 Release Notes 2.80S



New Features

Required Software Update

As John Deere continues to develop new technology, StarFire[™] Network changes were necessary to support the addition of new satellite constellations and additional enhancements. This required the introduction of a new signal.

StarFire[™] 3000 and StarFire[™] 6000 receivers must be updated to the 20-2 software update to continue operating on the new signal. Update all receivers prior to February 1, 2021 to avoid any interruption in function.

StarFire[™] iTC receivers will not function on the new signal beginning February 1, 2021 but will continue to operate in WAAS, EGNOS, or Non-Diff (depending on location) until approximately 2026.

Resolved Items

Direction Change Displayed Incorrectly in Slow Speed Integrated AutoTrac™

When traveling at slow speeds (below 0.5 kph/0.3 mph) and changing direction, direction of travel may not display correctly. This software update reduces the minimum speed from 0.5 kph to 0.1 kph for the system to determine correct direction of travel and resolve heading issues.

Release Notice

These are software release notes for the StarFire[™] 3000 Receiver. Release Notes can be found on www.stellarsupport.com. Note: Your use of the software is governed by the End User License Agreement included with the software.