

**48-in. Front Blade (model year 2006-2015 X500s)**

Code	Description	List price
6009M	48-in. Front Blade (model year 2006-2015 X500s) 1219 mm (48 in.) Cutting Width 1194 mm (47 in.) Cutting Width at 15 degree angle 1067 mm (42 in.) Cutting Width at 30 degree angle 5 Angling Positions Spring-Trip with Lock 3.05 mm (0.12 in.) Blade Thickness	
	BASE MACHINE <i>For Model Year 2006-2015 Select Series X500 M-T Tractors</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>F.O.B. Davenport, Iowa</i>	
6009M	48-in. Front Blade (model year 2006-2015 X500s)	USD \$1,125.00
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
M42868	Front blade rubber squeegee (48-in. and 54-in. blades) <i>48-in. (122-cm) Front Blade requires 7 03M7188 bolts and 7 14M7273 nuts.</i> <i>54-in. (137-cm) Front Blade requires 10 03M7188 bolts and 10 14M7273 nuts.</i>	USD \$96.63
LP64664	Snow plow markers <i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i>	USD \$39.99
AM119321	Heavy-duty skid shoe (1) <i>Optional upgrade on 48-in. (122-cm) Front Blades and 54-in. (137-cm) Quick Hitch Front Blade. Standard equipment on 60-in. (152-cm) Quick Hitch Front Blade. Two required.</i>	USD \$99.67
BM23448	Manual angling kit (48-in. Front Blade X394 and X500 M-T)	USD \$310.30

**44-in. Front Blade (model year 2016- X300s)**

Code	Description	List price
600AM	44-in. Front Blade (model year 2016- X300s) 1118 mm (44 in.) Cutting Width 1016 mm (40 in.) Cutting Width at 25 degree angle 3 Angling Positions 3.05 mm (0.12 in.) Blade Thickness	
	BASE MACHINE <i>For model year 2016- Select Series X300 tractors.</i> <i>X350R tractors require M167277 lift arm. See DTAC solution 117694 for more information.</i> http://dtac.deere.com/Solutions/English/117694.htm <i>Rear weights and tire chains are available for additional traction.</i> <i>Sales are restricted to the following countries: Australia, Austria, Belgium, Canada, Czech Republic, Denmark, Finland, France, Germany, Ireland, Italy, Japan, Luxembourg, Netherlands, New Zealand, Norway, Portugal, Poland, Spain, Sweden, Switzerland, United Kingdom, and United States.</i> <i>F.O.B. Davenport, Iowa</i>	
600AM	44-in. Front Blade (model year 2016- X300s)	USD \$825.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BUC10209	44-in Front Blade Spanish North American Operator's Manual and Decal kit (6005M for 2016- X300 Series)	USD \$49.21
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
LP33712	Manual angling kit (44-in. Front Blade X300s)	USD \$209.99
M146542	Front blade rubber squeegee (44-in. blade) <i>Requires 7 03M7188 bolts and 7 14M7273 nuts</i>	USD \$113.21
LP64865	Electric lift kit (model year 2016-)	USD \$799.99

**48-in. Front Blade (X394, model year 2016- X500s)**

Code	Description	List price
600BM	48-in. Front Blade (X394, model year 2016- X500s) 1219 mm (48 in.) Cutting Width 1194 mm (47 in.) Cutting Width at 15 degree angle 1067 mm (42 in.) Cutting Width at 30 degree angle 5 Angling Positions Spring-Trip with Lock 3.05 mm (0.12 in.) Blade Thickness	
	BASE MACHINE <i>For X394, and model year 2016- Select Series X500 M-T tractors.</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>Sales are restricted to the following countries: Australia, Austria, Belgium, Canada, Czech Republic, Denmark, Finland, France, Germany, Ireland, Italy, Japan, Luxembourg, Netherlands, New Zealand, Norway, Portugal, Poland, Spain, Sweden, Switzerland, United Kingdom, and United States.</i> <i>F.O.B. Davenport, Iowa</i>	
600BM	48-in. Front Blade (X394, model year 2016- X500s)	USD \$1,125.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BUC10208	48-in Front Blade Spanish North American Operator's Manual and Decal kit (6006M for 2016- X500 Series)	USD \$103.79
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
M42868	Front blade rubber squeegee (48-in. and 54-in. blades) 48-in. (122-cm) Front Blade requires 7 03M7188 bolts and 7 14M7273 nuts. 54-in. (137-cm) Front Blade requires 10 03M7188 bolts and 10 14M7273 nuts.	USD \$96.63
LP64664	Snow plow markers	USD \$39.99

**48-in. Front Blade (X394, model year 2016- X500s)**

Code	Description	List price
AM119321	<i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i> Heavy-duty skid shoe (1) <i>Optional upgrade on 48-in. (122-cm) Front Blades and 54-in. (137-cm) Quick Hitch Front Blade. Standard equipment on 60-in. (152-cm) Quick Hitch Front Blade. Two required.</i>	USD \$99.67
BM23448	Manual angling kit (48-in. Front Blade X394 and X500 M-T)	USD \$310.30
LP64865	Electric lift kit (model year 2016-) <i>For X394 and X570, not compatible with X580, X584, and X590.</i>	USD \$799.99

**44-in. Snow Blower (100 and 200 Series)**

Code	Description	List price
700CM	44-in. Snow Blower (100 and 200 Series) 44-in. (1118-mm) clearing width One-tool removal and re-installation 12-in. (305-mm) diameter auger Reversible and replaceable cutting blade 200-degree spout rotation Cast-iron gear box Sealed, anti-friction ball bearings Remote spout cap control Adjustable skid shoes	
	BASE MACHINE <i>NOTE: For use with model year 2015- 100 and 200 Series Tractors, and any model year 2014 tractors built after April 2014. This includes all 200 Series models, all 100 Series models with an S or E prefix, and the D-prefix models listed in this snow blower's Value Selling Navigator page.</i> <i>NOTE: Model year -2017 tractors will need to follow the instructions in CCMS solution 111809 to drill holes in the vehicle frame.</i> <i>NOTE: Requires two UC13263 suit case weights and one BG20627 rear weight bracket. Tire chains are recommended for additional traction.</i> <i>NOTE: Sales are restricted to the following countries: Canada and United States.</i> <i>F.O.B. Davenport, Iowa</i>	
700CM	44-in. Snow Blower (100 and 200 Series)	USD \$1,927.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
AM122263	Skid shoe, heavy-duty left-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$92.27
AM122264	Skid shoe, heavy-duty right-hand (1)	USD \$95.92

**44-in. Snow Blower (100 and 200 Series)**

Code	Description	List price
M88984	<i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i> Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies <i>NOTE: Compatibility with 100 and 200 Series snow blowers only goes as far back as 700AM.</i>	USD \$159.99
LP68150	Snow blower electric lift kit (for snow blower 700AM and 700BM on 100 Series and 200 Series)	USD \$699.99

**44-in. Snow Blower (model year 2006-2015 X300s, X500, X520)**

Code	Description	List price
700DM	44-in. Snow Blower (model year 2006-2015 X300s, X500, X520) 1118-mm (44-in.) Clearing Width Easy-On, Easy-Off Mounting 305-mm (12-in.) Diameter Auger Reversible and Replaceable Cutting Blade 200 degree Spout Rotation Cast Iron Gear Box Sealed, Anti-Friction Ball Bearings Remote Spout Cap Control Adjustable Skid Shoes	
	BASE MACHINE <i>For model year 2006-2015 Select Series tractors (model X300, X304, X310, X320, X324, X340, X360, X300R, X305R, model X500, and X520).</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>Winter grill cover recommended on model year 2006-2013 air-cooled engines to prevent carburetor icing.</i> <i>X300 and X304 tractors shipped with 38X, 42X, or less deck require AM136646 lift assist spring kit.</i> <i>X300-42M and X304-42M built with Edge Mulch deck with a single belt (model year 2006-2009, S.N. 010,001- 150,000) require AM136646 lift-assist spring kit.</i> <i>X320, X324, X340, model X500, and X520 tractors built prior to September 2006 (see Sales Manual for tractor serial number breaks) require the original M151924 lift-assist spring be replaced with AM136645 lift-assist spring.</i> <i>X300R and X305R tractors require collection hopper or a rear deflector kit. For snow blowers built prior to April 2008 (S.N. -030,001) see DTAC solution 79224 for adaptation instructions.</i> <i>Not for sale in France.</i> <i>F.O.B. Davenport, Iowa</i>	
700DM	44-in. Snow Blower (model year 2006-2015 X300s, X500, X520)	USD \$2,125.00
	MISCELLANEOUS	

**44-in. Snow Blower (model year 2006-2015 X300s, X500, X520)**

Code	Description	List price
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
AM122263	Skid shoe, heavy-duty left-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$92.27
AM122264	Skid shoe, heavy-duty right-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$95.92
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
AM135847	Snow blower and front blade replacement tractor side lift parts <i>Replaces the tractor mounted lift parts from a 2006-2015 44-in. Snow Blower (7001M/SKU23045), 47-in. Snow Blower (7002M/SKU23047), 44-in. Front Blade (6001M/SKU23044), or 48-in. Front Blade (6002M/SKU23048) for use on a model year 2006-2015 X300/X500 M-T tractor.</i>	USD \$430.82
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99

**47-in. Snow Blower (X530, X534, X540, model year 2015 X590)**

Code	Description	List price
700EM	47-in. Snow Blower (X530, X534, X540, model year 2015 X590) 1194 mm (47 in.) Clearing Width Easy-On, Easy-Off Mounting 406 mm (16 in.) Diameter Auger Reversible and Replaceable Cutting Blade 200 degree Spout Rotation Cast Iron Gear Box Sealed, Anti-Friction Ball Bearings Remote Spout Cap Control Adjustable Skid Shoes	
	BASE MACHINE <i>For model year 2006-2015 Select Series tractors (X530, X534, X540, and model year 2015 X590).</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>Winter grill cover recommended on model year 2006-2013 air-cooled engines to prevent carburetor icing.</i> <i>Also order M158756 spring and M174506 belt when used on model year 2015 X590 (serial 100,001-110,000).</i> <i>Not for sale in France.</i> <i>F.O.B. Davenport, Iowa</i>	
700EM	47-in. Snow Blower (X530, X534, X540, model year 2015 X590)	USD \$2,350.00
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
AM122263	Skid shoe, heavy-duty left-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$92.27
AM122264	Skid shoe, heavy-duty right-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$95.92
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
AM135847	Snow blower and front blade replacement tractor side lift	USD \$430.82

**47-in. Snow Blower (X530, X534, X540, model year 2015 X590)**

Code	Description	List price
	parts <i>Replaces the tractor mounted lift parts from a 2006-2015 44-in. Snow Blower (7001M/SKU23045), 47-in. Snow Blower (7002M/SKU23047), 44-in. Front Blade (6001M/SKU23044), or 48-in. Front Blade (6002M/SKU23048) for use on a model year 2006-2015 X300/X500 M-T tractor.</i>	
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99

**44-in. Snow Blower (model year 2016- X300s and X570)**

Code	Description	List price
700FM	44-in. Snow Blower (model year 2016- X300s and X570) 1118 mm (44 in.) Clearing Width Easy-On, Easy-Off Mounting 305 mm (12 in.) Diameter Auger Reversible and Replaceable Cutting Blade 200 degree Spout Rotation Cast Iron Gear Box Sealed, Anti-Friction Ball Bearings Remote Spout Cap Control Adjustable Skid Shoes	
	BASE MACHINE <i>For model year 2016- Select Series tractors (X330, X350, X354, X370, X380, X384, X390, X394, X350R, and X570).</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>X330, X350, and X354 tractors shipped with 42-in. Accel Deep mower deck or less deck require BM25887 lift assist spring kit.</i> <i>X350R tractors require BM24810 supplemental lift assist spring kit.</i> <i>X350R tractors require collection hopper or a rear deflector kit.</i> <i>Sales are restricted to the following countries: Austria, Belgium, Canada, Czech Republic, Denmark, Finland, France, Germany, Ireland, Italy, Luxembourg, Netherlands, Norway, Poland, Spain, Sweden, Switzerland, United Kingdom, and United States.</i> <i>F.O.B. Davenport, Iowa</i>	
700FM	44-in. Snow Blower (model year 2016- X300s and X570)	USD \$2,125.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
AM122263	Skid shoe, heavy-duty left-hand (1)	USD \$92.27

**44-in. Snow Blower (model year 2016- X300s and X570)**

Code	Description	List price
	<i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	
AM122264	Skid shoe, heavy-duty right-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$95.92
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57

**47-in. Snow Blower (X580, X584, model year 2016- X590)**

Code	Description	List price
700GM	47-in. Snow Blower (X580, X584, model year 2016- X590) 1194 mm (47 in.) Clearing Width Easy-On, Easy-Off Mounting 406 mm (16 in.) Diameter Auger Reversible and Replaceable Cutting Blade 200 degree Spout Rotation Cast Iron Gear Box Sealed, Anti-Friction Ball Bearings Remote Spout Cap Control Adjustable Skid Shoes	
	BASE MACHINE <i>For model year 2016- Select Series tractors (X580, X584, and model year 2016- X590).</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>Sales are restricted to the following countries: Austria, Belgium, Canada, Czech Republic, Denmark, Finland, France, Germany, Ireland, Italy, Luxembourg, Netherlands, Norway, Poland, Spain, Sweden, Switzerland, United Kingdom, and United States.</i> <i>F.O.B. Davenport, Iowa</i>	
700GM	47-in. Snow Blower (X580, X584, model year 2016- X590)	USD \$2,350.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
AM122263	Skid shoe, heavy-duty left-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$92.27
AM122264	Skid shoe, heavy-duty right-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$95.92
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock</i>	USD \$44.29

**47-in. Snow Blower (X580, X584, model year 2016- X590)**

Code	Description	List price
M157831	<i>nuts.</i> Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99

**42 in. Edge Xtra Deck (42X)**

Code	Description	List price
9039M	42 in. Edge Xtra Deck (42X) 42-in. (107-cm) cutting width Side discharge Edge™ Xtra 12-gauge, 0.105-in. (2.7-mm) stamped-steel deck shell Belt drive Two greaseable blade spindles Mower wash port Two front mower wheels	
	BASE MACHINE <i>For Model Year 2006-2015 Select Series Tractors (Model X300, X304, X310, X320, X324, X340, X360, Model X500, X520, X540, and Model Year 2015 X590). F.O.B. Janesville, Wisconsin.</i>	
9039M	42 in. Edge Xtra Deck (42X)	USD \$900.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
0202	United States and Canada	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30
	MULCH KITS	
BM21816	Mulching attachment, 42-in. (107-cm) or 42X	USD \$128.40

**48 in. Edge Xtra Deck (48X)**

Code	Description	List price
903SM	48 in. Edge Xtra Deck (48X) 48-in. (122-cm) cutting width Side discharge Edge™ Xtra 11-gauge, 0.120-in. (3-mm) stamped-steel deck shell Belt drive Three greaseable blade spindles Mower wash port Four mower wheels and front center roller Mower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>For Model Year 2006-2015 Select Series Tractors (Model X300, X304, X310, X320, X324, X340, X360, Model X500, X520, X534, X540, and Model Year 2015 X590).</i> <i>Also order AM136646 Lift Assist Spring Kit when used on X300-38, X300-42X, X300-Less deck, X304-42X, or with MY2006-MY2009 (Serial 010001-150,000) X300-42M tractors.</i> <i>F.O.B. Janesville, Wisconsin.</i>	
903SM	48 in. Edge Xtra Deck (48X)	USD \$1,480.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
0202	United States and Canada	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30
	MULCH KITS	
BM20007	Mulch kit (48C/48X)	USD \$207.59

**54-in. (137-cm) Quick-Hitch Snow Blower**

Code	Description	List price
02C2M	54-in. (137-cm) Quick-Hitch Snow Blower 54-in. (137-cm) clearing width Two-stage design 200-degree hydraulic discharge chute rotation 15-in. (381-mm) diameter impeller 16-in. (406-mm) diameter auger Shear bolt protection Adjustable spout cap deflector Reversible and replaceable scraper blade Four extra shell-mounted shear bolts Less front quick-hitch Less front PTO Less upstop and drive shaft	
	BASE MACHINE <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2305, 2025R, model year 2013-2016 2032R, 2320-2720 Tractors.</i> <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>See Sales Manual for ballast requirements.</i>	
02C2M	54-in. (137-cm) Quick-Hitch Snow Blower	USD \$3,525.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BLV11058	47-in. and 54-in. Quick Hitch Snowblower Spanish kit (CUTs)	USD \$103.79
	HITCHES Basic Factory Options FRONT HITCH	
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00
6952	Front quick-hitch	USD \$1,164.00

**54-in. (137-cm) Quick-Hitch Snow Blower**

Code	Description	List price
6956	<i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i> Front quick-hitch	USD \$1,207.00
6953	<i>For 1023E and 1025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch	USD \$1,175.00
6959	<i>For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.</i> Front quick-hitch	USD \$1,219.00
6943	<i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch	USD \$753.00
6963	<i>For 2305 Tractor. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i> Front quick-hitch	USD \$823.00
6967	<i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, and 2720 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, and 2720 Tractors require LVB25302 front attaching support.</i> Less front hitch	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20



54-in. (137-cm) Quick-Hitch Snow Blower

Code	Description	List price
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s)	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
ATTACHING COMPONENTS Basic Factory Options MOUNTING KIT / DRIVESHAFT		
6838	Snow blower upstop and drive shaft <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BUC11685 snow blower upstop and drive shaft.</i>	USD \$318.00
6840	Snow blower upstop and drive shaft <i>For 2305, 1023E, 1025R, 1026R, and model year 2017 and newer 2025R. Includes BLV10899 snow blower drive shaft and BLV10793 upstop.</i>	USD \$485.00
6842	Snow blower upstop and drive shaft <i>For model year 2013-2016 2025R, 2013-2016 2032R, 2320, 2520, and 2720 Tractors. Includes BUC11684 snow blower upstop and drive shaft.</i>	USD \$332.00
6835	Less mounting kit and drive shaft	In Base Price
POWER TAKE-OFF Basic Factory Options FRONT POWER TAKE-OFF (PTO)		
6889	2000-rpm front PTO (2-wheel drive) <i>For X400 Heavy-Duty Garden, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754 Tractors. Includes BM25304 2000-rpm front PTO. Must be used with BM25775 broom drive shaft, BM25772 implement drive and upstop, or BUC11685 snow blower upstop and drive shaft.</i>	USD \$399.00



54-in. (137-cm) Quick-Hitch Snow Blower

Code	Description	List price
6890	2000-rpm front PTO (4-wheel drive) <i>For X500 Heavy-Duty Garden, X728, X729, X748, X749, X738, X739, and X758 Tractors. Includes BM25305 2000-rpm front PTO.</i>	USD \$399.00
6887	2000-rpm front PTO <i>For 1023E, 1025R, and 1026R Tractors. Includes BLV10786 2000-rpm front PTO. See DTAC solution 111853 when used with BLV10159 front quick-hitch.</i>	USD \$500.00
6888	2000-rpm front PTO <i>For model year 2017 and newer 2025R Tractors. Includes BLV10681 2000-rpm front PTO.</i>	USD \$408.00
6885	2000-rpm front PTO <i>For model year 2013-2016 2032R, 2520, and 2720 Tractors. Includes BLV10475 2000-rpm front PTO.</i>	USD \$329.00
6895	2000-rpm front PTO <i>For 2305 Tractors. Includes LVB25966 2000-rpm front PTO.</i>	USD \$348.00
6896	2000-rpm front PTO. <i>For model year 2013-2016 2025R, and 2320 Tractors. Includes LVB24900 2000-rpm front PTO.</i>	USD \$320.00
6910	Less 2000-rpm front PTO	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT POWER TAKE-OFF (PTO)		
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i>	USD \$587.43
	<i>Includes shaft to route mid-PTO to the front-PTO.</i>	
	<i>Includes front bearing and support structure.</i>	
	<i>Includes RIO override for front implements.</i>	



54-in. (137-cm) Quick-Hitch Snow Blower

Code	Description	List price
BLV10681	See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm 2000 RPM Front PTO For model year 2017- 2025R, and 2026R.	USD \$479.36
BM25304	Includes shaft to route mid-PTO to the front-PTO. Includes front bearing and support structure. Includes RIO override for front implements. 2000-rpm front PTO (X400 and 2-wheel drive X700s) BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.	USD \$456.89
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE AND UPSTOP		
BLV10793	Snow Blower Attaching Kit (Upstop) For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$220.41
BLV10899	Snow Blower Drive Shaft For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$349.89
MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS		
M88984	Drift blade For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.	USD \$44.29
LVB25396	Front Attaching Support Kit (2305)	USD \$139.10



54-in. (137-cm) Quick-Hitch Snow Blower

Code	Description	List price
BM20960	2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements. Remote spout cap control kit For 425-455, 318, 322, 332, 420, 430, X400/X500 HDGT's, F900's, X700's, 2210, 2305, 4010, 4100, 4110, 4115 Tractors. See Sales Manual for required attaching parts.	USD \$154.09
LVB24958	Remote Spout Cap Control Kit For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, and 2720 tractors. See Sales Manual for required attaching parts.	USD \$184.04
AM128336	Right-side skid shoe plate and hardware	USD \$70.06
AM128337	Left-side skid shoe plate and hardware	USD \$68.73
M157831	Skid shoe, plastic (1) Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99
BLV10843	Remote Spout Kit Fits 1023E, 1025R, 1026R and 2025R Tractors. Requires BLV10720 electric remote spout cap control chassis harness.	USD \$335.99
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) 2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
BXX11138	Remote Spout Control Kit Includes tractor-side harnesses, switch, and hardware to adjust snow blower spout cap from the tractor seat. 1023E and 1025R require BXX10391 junction block kit.	USD \$299.50
LVB26213	Remote Spout Cap Control Kit For 1023E, 1025R, and 1026R open-station Tractors. Not compatible with cab.	USD \$248.24

54-in. (137-cm) Quick-Hitch Snow Blower

Code	Description	List price
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70

**62-in. Shaft Drive Convertible/Edge Xtra Mower Deck (62C/62X)**

Code	Description	List price
9072M	62-in. Shaft Drive Convertible/Edge Xtra Mower Deck (62C/62X) 62-in. (157-cm) cutting width Side discharge Edge™ Xtra 10-gauge, 0.135-in. (3.4-mm) stamped-steel deck shell Shaft drive Three greaseable blade spindles Mower wash port Four mower wheels and front center roller Mower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>For X400/X500 HDGTs (Heavy-Duty Garden Tractors), Model Year 2006-2012 X700 Series, 2210 and 2305 Compact Utility Tractors. F.O.B. Horicon, Wisconsin</i>	
9072M	62-in. Shaft Drive Convertible/Edge Xtra Mower Deck (62C/62X)	USD \$2,375.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
0202	United States and Canada	In Base Price
0195	Mexico	No Added Cost
	ATTACHING COMPONENTS Basic Factory Options ATTACHING PARTS	
1000	Attaching Parts for 2305, 2210 (Mechanical Mower Lift)	USD \$277.00
1001	Attaching Parts for 2305 (Independent Mower Lift) <i>Independent Lift is not Available on 2210.</i>	USD \$551.00
1010	Less Attaching Parts <i>Order when mower deck will be used on X400/X500 HDGTs (heavy-duty garden tractors) or X700s.</i>	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION ATTACHING PARTS	
LVB25630	Independent Lift Kit for 2305, 2025R, 2320 Tractors <i>Requires LVB25620 (option code 1001) attaching parts. Requires LVB25631 (independent lift attaching parts). Not available for 2210 tractors.</i>	USD \$559.90

**62-in. Shaft Drive Convertible/Edge Xtra Mower Deck (62C/62X)**

Code	Description	List price
LVB25419	Attaching Parts for 2305, 2210 (Mechanical Mower Lift)	USD \$617.10
LVB25631	Attaching Parts for 2305 (Independent Mower Lift) <i>Requires LVB25630 independent lift kit. Not available for 2210 tractors.</i>	USD \$265.10
MOWER DECK		
ATTACHMENTS FOR FIELD CONVERSION		
MULCH KITS		
BM21890	Mulch kit (62C/62D/62X)	USD \$354.17
MOWER DECKS		
AM130907	Mower deck leveling gauge	USD \$8.30
BM23648	Roller striping kit (X400/X500 HDGT, X700s) <i>Compatible with model year 2004- (SN 040, 001-) 54C, 54X, 62X, and 60-in. (152-cm) 7-Iron Mowers used on X400/X500 HDGT and X700 Ultimate Tractors. See Sales Manual for additional parts requirements on model year 2004-2007 (SN 040,001-100,000) 54C, 54X, 62C and 62X Decks.</i>	USD \$378.79
HYDRAULICS		
ATTACHMENTS FOR FIELD CONVERSION		
HYDRAULICS		
LVB25822	Loader and Mower Mechanical Diverter Valve Kit (2305, 2025R, 2320) <i>Diverter is not compatible with mechanical mower lift system.</i>	USD \$734.01

**48-in. Shaft Drive Accel Deep Mower Deck (48A)**

Code	Description	List price
907AM	48-in. Shaft Drive Accel Deep Mower Deck (48A) 48-in. (122-cm) cutting width Side discharge Accel Deep™ 10-gauge, 0.135-in. (3.4-mm) stamped-steel deck shell Shaft drive Three greaseable blade spindles Mower wash port Four mower wheels and front center roller Mower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>For X700 Signature Series (Model Year 2013-).</i> <i>Painted green to align mowing trade dress.</i> <i>F.O.B. Horicon, Wisconsin</i>	
907AM	48-in. Shaft Drive Accel Deep Mower Deck (48A)	USD \$1,925.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	United States and Canada	In Base Price
	POWER TAKE-OFF Basic Factory Options POWER TAKE-OFF (PTO) CONNECTION	
3425	Standard Connect	In Base Price
3426	Auto Connect	USD \$259.00
3490	Less Drive Shaft	USD (\$190.00)
	ATTACHMENTS FOR FIELD CONVERSION POWER TAKE-OFF (PTO) CONNECTION	
BM25677	AutoConnect attachment, X700 Signature Series and X940s	USD \$598.13
BM25678	Standard drive shaft with hanger, X700 Signature Series and X940s	USD \$254.66
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30

**54-in. Shaft Drive High Capacity Mower Deck (54 HC)**

Code	Description	List price
907BM	54-in. Shaft Drive High Capacity Mower Deck (54 HC) 54-in. (137-cm) cutting width Side discharge High Capacity 9-gauge, 0.150-in. (3.8-mm) stamped-steel deck shell Shaft drive Three greaseable blade spindles Mower wash port Four mower wheels Drive-over deck mower installation/removal	
	BASE MACHINE <i>For X700 Signature Series (model year 2013-) Painted green to align mowing trade dress. F.O.B. Horicon, Wisconsin</i>	
907BM	54-in. Shaft Drive High Capacity Mower Deck (54 HC)	USD \$2,275.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	United States and Canada	In Base Price
	POWER TAKE-OFF Basic Factory Options POWER TAKE-OFF (PTO) CONNECTION	
3425	Standard Connect	In Base Price
3426	Auto Connect	USD \$259.00
3490	Less Drive Shaft	USD (\$190.00)
	ATTACHMENTS FOR FIELD CONVERSION POWER TAKE-OFF (PTO) CONNECTION	
BM25677	AutoConnect attachment, X700 Signature Series and X940s	USD \$598.13
BM25678	Standard drive shaft with hanger, X700 Signature Series and X940s	USD \$254.66
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MULCH KITS	
BM23977	54 HC Mulch kit	USD \$314.59
BM26300	54-in. High Capacity MulchControl attachment	USD \$406.60



54-in. Shaft Drive High Capacity Mower Deck (54 HC)

Code	Description	List price
MOWER DECKS		
AM130907	Mower deck leveling gauge	USD \$8.30

**60-in. Shaft Drive High Capacity Mower Deck (60 HC)**

Code	Description	List price
907CM	60-in. Shaft Drive High Capacity Mower Deck (60 HC) 60-in. (152-cm) cutting width Side discharge High Capacity 9-gauge, 0.150-in. (3.8-mm) stamped-steel deck shell Shaft drive Three greaseable blade spindles Mower wash port Four mower wheels Drive-over deck mower installation/removal	
	BASE MACHINE <i>For X700 Signature Series (model year 2013-).</i> <i>Painted green to align mowing trade dress."</i> <i>F.O.B. Horicon, Wisconsin</i>	
907CM	60-in. Shaft Drive High Capacity Mower Deck (60 HC)	USD \$2,800.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	United States and Canada	In Base Price
	POWER TAKE-OFF Basic Factory Options POWER TAKE-OFF (PTO) CONNECTION	
3425	Standard Connect	In Base Price
3426	Auto Connect	USD \$259.00
3490	Less Drive Shaft	USD (\$190.00)
	ATTACHMENTS FOR FIELD CONVERSION POWER TAKE-OFF (PTO) CONNECTION	
BM25677	AutoConnect attachment, X700 Signature Series and X940s	USD \$598.13
BM25678	Standard drive shaft with hanger, X700 Signature Series and X940s	USD \$254.66
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30
	MULCH KITS	



60-in. Shaft Drive High Capacity Mower Deck (60 HC)

Code	Description	List price
BM25258	60-in. High Capacity MulchControl attachment	USD \$434.41
BM23978	60 HC Mulch kit	USD \$327.41



ROPS Hard Cab

Code	Description	List price
9356M	ROPS Hard Cab Modular Design Roll-Over Protective Structure (ROPS) Certified Steel Doors Sliding Glass Windows Front windshield wiper Safety Glass Rear Window	
	BASE MACHINE <i>For X700 Signature Series Tractors (X710, X730, X734, X738, X739, X750, X754, and X758)</i> <i>F.O.B. Davenport, Iowa</i>	
9356M	ROPS Hard Cab	USD \$8,375.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US and Canada	In Base Price
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
BM25033	Heater, Tuck-Away	USD \$572.46
BM25061	Rear wiper kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$255.73
BM25062	Mirror kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$155.16
BM25063	Strobe light kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$329.56
BM25064	Switch-panel fuse block kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$385.20
BM25082	Work light kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$282.49
BM25094	Heater quick connect kit (X710,X730,X734,X738,X739,X750,X754,X758)	USD \$243.96
BM25081	Interior rear-view mirror kit (X710, X730, X734, X738, X739, X750, X754, X758)	USD \$134.81
BUC10188	Auxiliary alternator kit (X710, X730, X734, X738, X739) <i>Supplements standard 20-amp alternator. Recommended with heated cabs.</i>	USD \$736.16



60-in. (152-cm) Quick-Hitch Front Blade

Code	Description	List price
9821M	60-in. (152-cm) Quick-Hitch Front Blade 60-in. (152-cm) clearing width straight 53.5-in. (136-cm) clearing width angled Replaceable cutting edge Heavy 7-gauge, curved blade angled left or right up to 27 degrees Two-adjustable heavy-duty skid shoes Reinforced angle bar on back of blade spring breakaway with lock-out pin	
	BASE MACHINE <i>For 425, 445, 455, X400/X500 Heavy Duty Garden Tractors, X700s, X940s, X950R, 1023E, 1025R, 1026R, 2210, 2305, 2025R, 2026R, 2027R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110 and 4115 Tractors</i> <i>BM20761 hydraulic coupler kit required on 425, X465, X475, X700, and X710 Tractors.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>See Sales Manual for ballast requirements.</i>	
9821M	60-in. (152-cm) Quick-Hitch Front Blade	USD \$1,325.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	HITCHES Basic Factory Options FRONT HITCH	
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00
6952	Front quick-hitch <i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i>	USD \$1,164.00
6956	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic</i>	USD \$1,207.00

**60-in. (152-cm) Quick-Hitch Front Blade**

Code	Description	List price
6957	connector. Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder. Front quick-hitch For 1023E and 1025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.	USD \$1,363.00
6953	Front quick-hitch For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.	USD \$1,175.00
6959	Front quick-hitch For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.	USD \$1,219.00
6960	Front quick-hitch For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation	USD \$1,375.00



60-in. (152-cm) Quick-Hitch Front Blade

Code	Description	List price
6943	cylinder. Front quick-hitch <i>For 2210 and 2305 Tractors. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i>	USD \$753.00
6963	Front quick-hitch <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, 2720, 4100, 4110, and 4115 Tractors require LVB25302 front attaching support. 4010 Tractors require LVB25293 front attaching support. LVB25293 must be built from component parts.</i>	USD \$823.00
6967	Less front hitch	In Base Price
HYDRAULIC ANGLING		
6800	HYDRAULIC ANGLING <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25609 hydraulic angling.</i>	USD \$225.00
6805	Hydraulic angling <i>For 1023E, 1025R, 1026R, model year 2017 and newer 2025R, and 2026R Tractors. Includes BLV10880 hydraulic angling.</i>	USD \$298.00
6802	Hydraulic angling <i>For 2210 and 2305 Tractors. Includes BM20922 hydraulic angling.</i>	USD \$227.00
6803	Hydraulic angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, 4010, 4110 and 4115 Tractors. Includes LVB24901 hydraulic angling.</i>	USD \$227.00
6818	Less Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year	USD \$325.29



60-in. (152-cm) Quick-Hitch Front Blade

Code	Description	List price
BLV10880	2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115) Hydraulic Angling FRONT QUICK-HITCH	USD \$349.89
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS		
LP64664	Snow plow markers <i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i>	USD \$39.99
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
AM119321	Heavy-duty skid shoe (1)	USD \$99.67
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year	USD \$182.60

**60-in. (152-cm) Quick-Hitch Front Blade**

Code	Description	List price
LVB25302	2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i> Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70



47-in. (119-cm) Quick-Hitch Snow Blower

Code	Description	List price
1475M	47-in. (119-cm) Quick-Hitch Snow Blower 47-in. (119-cm) clearing width Two-stage design 200-degree hydraulic discharge chute rotation 15-in. (381-mm) diameter impeller 16-in. (406-mm) diameter auger Shear bolt protection Adjustable spout cap deflector Reversible and replaceable scraper blade Four extra shell-mounted shear bolts Less front quick-hitch Less front PTO Less upstop and drive shaft	
	BASE MACHINE <i>For 425, 445, 455, X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2210, 2305, 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, and 4110 Tractors. BM20761 hydraulic coupler kit required on 425, X465, X475, X700, and X710 Tractors. Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements. See Sales Manual for ballast requirements.</i>	
1475M	47-in. (119-cm) Quick-Hitch Snow Blower	USD \$2,975.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BLV11058	47-in. and 54-in. Quick Hitch Snowblower Spanish kit (CUTs)	USD \$103.79
	HITCHES Basic Factory Options FRONT HITCH	
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00
6952	Front quick-hitch	USD \$1,164.00

**47-in. (119-cm) Quick-Hitch Snow Blower**

Code	Description	List price
6956	<i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i> Front quick-hitch	USD \$1,207.00
6953	<i>For 1023E and 1025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch	USD \$1,175.00
6959	<i>For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.</i> Front quick-hitch	USD \$1,219.00
6947	<i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch	USD \$1,023.00
6943	<i>For 425, 445, and 455 Tractors. Includes BM17347 front quick-hitch.</i> Front quick-hitch	USD \$753.00
6963	<i>For 2210 and 2305 Tractors. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i> Front quick-hitch	USD \$823.00
	<i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, 2720, 4100, 4110, and 4115 Tractors require LVB25302 front attaching support. 4010 Tractors require</i>	



47-in. (119-cm) Quick-Hitch Snow Blower

Code	Description	List price
6967	<i>LVB25293 front attaching support. LVB25293 must be built from component parts.</i> Less front hitch	In Base Price
ATTACHMENTS FOR FIELD CONVERSION FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM20896	Hydraulic retro kit <i>Required to fit a customer's 425, 445 and 455 snow blower or snow thrower on a new X400/X500 HDGT or X700 Series tractor.</i>	USD \$38.51
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s)	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
ATTACHING COMPONENTS Basic Factory Options MOUNTING KIT / DRIVESHAFT		
6838	Snow blower upstop and drive shaft <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BUC11685 snow blower upstop and drive shaft.</i>	USD \$318.00
6840	Snow blower upstop and drive shaft <i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017 and newer 2025R. Includes BLV10899 snow blower drive shaft and BLV10793 upstop.</i>	USD \$485.00
6841	Snow blower upstop and drive shaft <i>For 425, 445, and 455 Tractors. Includes BUC11686 snow blower upstop and drive shaft.</i>	USD \$288.00
6842	Snow blower upstop and drive shaft	USD \$500.00



47-in. (119-cm) Quick-Hitch Snow Blower

Code	Description	List price
6835	<i>For model year 2013-2016 2025R, 2013-2016 2032R, 2320, 2520, 2720, 4100, and 4110 Tractors. Includes BXX11139 snow blower upstop and drive shaft.</i> Less mounting kit and drive shaft	In Base Price
POWER TAKE-OFF Basic Factory Options FRONT POWER TAKE-OFF (PTO)		
6889	2000-rpm front PTO (2-wheel drive) <i>For X400 Heavy-Duty Garden, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754 Tractors. Includes BM25304 2000-rpm front PTO. Must be used with BM25775 broom drive shaft, BM25772 implement drive and upstop, or BUC11685 snow blower upstop and drive shaft.</i>	USD \$399.00
6890	2000-rpm front PTO (4-wheel drive) <i>For X500 Heavy-Duty Garden, X728, X729, X748, X749, X738, X739, and X758 Tractors. Includes BM25305 2000-rpm front PTO.</i>	USD \$399.00
6887	2000-rpm front PTO <i>For 1023E, 1025R, and 1026R Tractors. Includes BLV10786 2000-rpm front PTO. See DTAC solution 111853 when used with BLV10159 front quick-hitch.</i>	USD \$500.00
6888	2000-rpm front PTO <i>For model year 2017 and newer 2025R Tractors. Includes BLV10681 2000-rpm front PTO.</i>	USD \$408.00
6885	2000-rpm front PTO <i>For model year 2013-2016 2032R, 2520, and 2720 Tractors. Includes BLV10475 2000-rpm front PTO.</i>	USD \$329.00
6894	2000-rpm front PTO <i>For 425, 445, and 455 Tractors. Includes BM17330 2000-rpm front PTO.</i>	USD \$299.00
6895	2000-rpm front PTO <i>For 2210 and 2305 Tractors. Includes LVB25966 2000-rpm front PTO.</i>	USD \$348.00
6897	2000-rpm front PTO	USD \$320.00



47-in. (119-cm) Quick-Hitch Snow Blower

Code	Description	List price
6910	<i>For 4100 and 4110 Tractors. Includes BM18695 2000-rpm front PTO.</i> Less 2000-rpm front PTO ATTACHMENTS FOR FIELD CONVERSION FRONT POWER TAKE-OFF (PTO)	In Base Price
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i>	USD \$587.43
BLV10681	<i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> <i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i> 2000 RPM Front PTO <i>For model year 2017- 2025R, and 2026R.</i>	USD \$479.36
BM17330	2000-rpm front power take-off (PTO) (415, 425, 445, 455)	USD \$347.76
BM25304	2000-rpm front PTO (X400 and 2-wheel drive X700s) <i>BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary</i>	USD \$456.89



47-in. (119-cm) Quick-Hitch Snow Blower

Code	Description	List price
	brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.	
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
	IMPLEMENT DRIVE AND UPSTOP	
BLV10793	Snow Blower Attaching Kit (Upstop) For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$220.41
BLV10899	Snow Blower Drive Shaft For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$349.89
	MISCELLANEOUS	
	ATTACHMENTS FOR FIELD CONVERSION	
	MISCELLANEOUS	
M88984	Drift blade For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.	USD \$44.29
LVB25396	Front Attaching Support Kit (2305) 2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.	USD \$139.10
BM20960	Remote spout cap control kit For 425-455, 318, 322, 332, 420, 430, X400/X500 HDGT's, F900's, X700's, 2210, 2305, 4010, 4100, 4110, 4115 Tractors. See Sales Manual for required attaching parts.	USD \$154.09
LVB24958	Remote Spout Cap Control Kit For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, and 2720 tractors. See Sales Manual for required attaching parts.	USD \$184.04
AM119321	Heavy-duty skid shoe (1) For 47-in. Quick Hitch Snow Blowers (SN -060,000)	USD \$99.67
AM128336	Right-side skid shoe plate and hardware	USD \$70.06
AM128337	Left-side skid shoe plate and hardware	USD \$68.73

**47-in. (119-cm) Quick-Hitch Snow Blower**

Code	Description	List price
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99
BLV10843	Remote Spout Kit <i>Fits 1023E, 1025R, 1026R and 2025R Tractors. Requires BLV10720 electric remote spout cap control chassis harness.</i>	USD \$335.99
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
BXX11138	Remote Spout Control Kit <i>Includes tractor-side harnesses, switch, and hardware to adjust snow blower spout cap from the tractor seat. 1023E and 1025R require BXX10391 junction block kit.</i>	USD \$299.50
LVB26213	Remote Spout Cap Control Kit <i>For 1023E, 1025R, and 1026R open-station Tractors. Not compatible with cab.</i>	USD \$248.24
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70



54-in. (137-cm) Quick-Hitch Front Blade

Code	Description	List price
1493M	54-in. (137-cm) Quick-Hitch Front Blade 54-in. (137-cm) clearing width straight 48-in. (122-cm) clearing width angled Replaceable cutting edge Heavy 11-gauge, curved blade angled left or right up to 27 degrees Two-adjustable skid shoes Reinforced angle bar on back of blade spring breakaway with lock-out pin	
	BASE MACHINE <i>For 425, 445, 455, X400/X500 Heavy Duty Garden Tractors, X700s, 1023E, 1025R, 2210, 2305, 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110 and 4115 Tractors. BM20761 hydraulic coupler kit required on 425, X465, X475, X700, and X710 Tractors. Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements. See Sales Manual for ballast requirements.</i>	
1493M	54-in. (137-cm) Quick-Hitch Front Blade	USD \$800.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	HITCHES Basic Factory Options FRONT HITCH	
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00
6952	Front quick-hitch <i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i>	USD \$1,164.00
6956	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10796 front</i>	USD \$1,207.00

**54-in. (137-cm) Quick-Hitch Front Blade**

Code	Description	List price
6957	<i>attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	USD \$1,363.00
6953	Front quick-hitch <i>For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.</i>	USD \$1,175.00
6959	Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i>	USD \$1,219.00
6960	Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	USD \$1,375.00

**54-in. (137-cm) Quick-Hitch Front Blade**

Code	Description	List price
6947	Front quick-hitch <i>For 425, 445, and 455 Tractors. Includes BM17347 front quick-hitch.</i>	USD \$1,023.00
6943	Front quick-hitch <i>For 2210 and 2305 Tractors. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i>	USD \$753.00
6963	Front quick-hitch <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, 2720, 4100, 4110, and 4115 Tractors require LVB25302 front attaching support. 4010 Tractors require LVB25293 front attaching support. LVB25293 must be built from component parts.</i>	USD \$823.00
6967	Less front hitch	In Base Price
HYDRAULIC ANGLING		
6800	HYDRAULIC ANGLING <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25609 hydraulic angling.</i>	USD \$225.00
6805	Hydraulic angling <i>For 1023E, 1025R, 1026R, model year 2017 and newer 2025R, and 2026R Tractors. Includes BLV10880 hydraulic angling.</i>	USD \$298.00
6801	Hydraulic angling <i>For 425, 445, and 455 Tractors. Includes BM17650 hydraulic angling.</i>	USD \$196.00
6802	Hydraulic angling <i>For 2210 and 2305 Tractors. Includes BM20922 hydraulic angling.</i>	USD \$227.00
6803	Hydraulic angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, 4010, 4110 and 4115 Tractors. Includes LVB24901 hydraulic angling.</i>	USD \$227.00
6818	Less Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		



54-in. (137-cm) Quick-Hitch Front Blade

Code	Description	List price
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BM17650	Hydraulic angling (415, 425, 445, 455)	USD \$230.06
BLV10880	Hydraulic Angling	USD \$349.89
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM17347	Front quick hitch and hydraulic lift (415, 425, 445, 455)	USD \$1,201.61
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
MISCELLANEOUS		
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
M42868	Front blade rubber squeegee (48-in. and 54-in. blades) <i>48-in. (122-cm) Front Blade requires 7 03M7188 bolts and 7 14M7273 nuts.</i> <i>54-in. (137-cm) Front Blade requires 10 03M7188 bolts and 10 14M7273 nuts.</i>	USD \$96.63
LP64664	Snow plow markers <i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i>	USD \$39.99
LVB25396	Front Attaching Support Kit (2305)	USD \$139.10

**54-in. (137-cm) Quick-Hitch Front Blade**

Code	Description	List price
AM119321	<i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i> Heavy-duty skid shoe (1) <i>Optional upgrade on 48-in. (122-cm) Front Blades and 54-in. (137-cm) Quick Hitch Front Blade. Standard equipment on 60-in. (152-cm) Quick Hitch Front Blade. Two required.</i>	USD \$99.67
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
3791M	60-in. (152-cm) Heavy-Duty Rotary Broom 57-in. (145-cm) clearing width straight 53.5-in. (136-cm) clearing width angled at 27 degrees with quick-hitch 50-in. (127-cm) clearing width angled at 30 degrees with front 3-point hitch Storage stands 26-in. (660-mm) diameter polypropylene brush Gearbox with 3:1 reduction Chain and sprocket final drive Two adjustable rear-mounted caster wheels Broom head float Four spare driveshaft shear bolts in two sizes mounted to shell	
	BASE MACHINE <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2305, 2025R, 2032R, 2036R, 2038R, 2320, 2520, 2720, 3120-3720, 3033R-3046R, 2210, 4100, and 4110. BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors. See Sales Manual for ballast requirements. Not compatible with BM17347, 400-Series Quick-Hitch. Compact tractors require dual selective control valve and mid PTO. Small chassis compact tractors also require front attaching support kit. See Sales Manual for front attaching support requirements. 3120-3720 Tractors with mid-mount mowers for use with front three-point hitch with A-Frame require LVB25820 (AutoConnect decks) or LVB24810 (old 7-Iron decks).</i>	
3791M	60-in. (152-cm) Heavy-Duty Rotary Broom	USD \$4,700.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BLV11054	52-in. Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$117.70
BLV11056	60-in. Heavy-Duty Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$119.84
	HITCHES	



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
Basic Factory Options		
FRONT HITCH		
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00
6952	Front quick-hitch <i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i>	USD \$1,164.00
6956	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i>	USD \$1,207.00
6957	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	USD \$1,363.00
6953	Front quick-hitch <i>For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.</i>	USD \$1,175.00
6959	Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch</i>	USD \$1,219.00



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
6960	<i>lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i> Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	USD \$1,375.00
6951	Front 3-point hitch with A-frame quick attach system <i>For model year 2017 and newer 2032R and 2038R Tractors. Includes BXX10836 front 3-point hitch, BLV10637 A-frame quick attach system, and BLV10634 auxiliary front hydraulic coupler kit.</i>	USD \$1,872.00
6950	Front 3-point hitch with A-frame quick attach system <i>For 3033R-3046R and 3120-3720 Tractors. Includes BLV10439 front 3-point hitch, BLV10637 A-frame quick attach system, and BLV10452 front power take off bracket.</i>	USD \$1,872.00
6943	Front quick-hitch <i>For 2210 and 2305 Tractors. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i>	USD \$753.00
6963	Front quick-hitch <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, 2720, 4100, 4110, and 4115 Tractors require LVB25302 front attaching support. 4010 Tractors require LVB25293 front attaching support. LVB25293 must be built from component parts.</i>	USD \$823.00
6967	Less front hitch HYDRAULIC ANGLING	In Base Price



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
6800	HYDRAULIC ANGLING <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25609 hydraulic angling.</i>	USD \$225.00
6805	Hydraulic angling <i>For 1023E, 1025R, 1026R, model year 2017 and newer 2025R, and 2026R Tractors. Includes BLV10880 hydraulic angling.</i>	USD \$298.00
6802	Hydraulic angling <i>For 2210 and 2305 Tractors. Includes BM20922 hydraulic angling.</i>	USD \$227.00
6803	Hydraulic angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, 4010, 4110 and 4115 Tractors. Includes LVB24901 hydraulic angling.</i>	USD \$227.00
6818	Less Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BLV10880	Hydraulic Angling	USD \$349.89
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BLV10634	Auxiliary Front Hydraulic Coupler Kit <i>Includes couplers, hoses, and brackets to route hydraulics from the mid-SCV to the front three-point hitch.</i>	USD \$371.80
BLV10638	Hydraulic accumulator kit for front 3-point hitch <i>For use in applications where there is significant transporting done at higher speeds. Accumulator system will absorb the bounce associated with front implements when traveling on the roadway.</i>	USD \$433.40
BLV10637	A-frame quick-attach system Category 1N	USD \$377.30
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016	USD \$1,216.59

**60-in. (152-cm) Heavy-Duty Rotary Broom**

Code	Description	List price
BM26236	2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i> Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BLV10439	Front 3-point hitch (3033R-3046R) <i>Requires BLV10452 (Front PTO Bracket).</i>	USD \$1,836.00
BM20921	Front Quick-Hitch and Hydraulic Lift (2305)	USD \$1,112.80
ATTACHING COMPONENTS		
Basic Factory Options		
MOUNTING KIT / DRIVESHAFT		
6844	Broom mounting kit and drive shaft <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25775 broom drive shaft, and BM20626 60-in. rotary broom mounting frame.</i>	USD \$806.00
6848	Broom mounting kit and drive shaft <i>For 1023E, 1025R, 1026R, and model year 2017 and newer 2025R Tractors. Includes BLV10900 broom drive shaft and BLV10795 mounting frame.</i>	USD \$855.00
6849	Broom mounting kit, drive shaft, and hydraulic angling <i>For model year 2017 and newer 2032R, and 2038R Tractors. Includes BLV10776 60-in. rotary broom mounting frame with hydraulic angling and BLV10800 60-in. rotary broom drive shaft.</i>	USD \$1,062.00
6850	Broom mounting kit, drive shaft, and hydraulic angling <i>For 3033R-3046R and 3120-3720 Tractors. Includes BLV10776 60-in. rotary broom mounting frame with hydraulic angling and LVB24956 60-in. rotary broom drive shaft.</i>	USD \$931.00
6853	Broom mounting kit and drive shaft <i>For 2210 and 2305 Tractors. Includes BLV10900 broom drive shaft and BM20626 60-in. rotary broom mounting frame.</i>	USD \$753.00
6852	Broom mounting kit and drive shaft <i>Add note: For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100 and 4110 Tractors. Includes</i>	USD \$652.00



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
6835	<i>BM20836 broom drive shaft BM20626 60-in. rotary broom mounting frame.</i> Less mounting kit and drive shaft	In Base Price
ATTACHMENTS FOR FIELD CONVERSION MOUNTING FRAME		
BM20626	60-in. Rotary Broom mounting frame <i>For use on X400/X500 HDGT's, X700s, 2210, 2305, model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$545.70
BLV10776	Mounting Frame and Hydraulic Angling (3120-3720, 3033R-3046R, model year 2017- 2032R, 2036R, and 2038R)	USD \$1,070.00
BLV10795	60-in. Rotary Broom mounting frame <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$666.61
POWER TAKE-OFF Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		
6889	2000-rpm front PTO (2-wheel drive) <i>For X400 Heavy-Duty Garden, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754 Tractors. Includes BM25304 2000-rpm front PTO. Must be used with BM25775 broom drive shaft, BM25772 implement drive and upstop, or BUC11685 snow blower upstop and drive shaft.</i>	USD \$399.00
6890	2000-rpm front PTO (4-wheel drive) <i>For X500 Heavy-Duty Garden, X728, X729, X748, X749, X738, X739, and X758 Tractors. Includes BM25305 2000-rpm front PTO.</i>	USD \$399.00
6887	2000-rpm front PTO <i>For 1023E, 1025R, and 1026R Tractors. Includes BLV10786 2000-rpm front PTO. See DTAC solution 111853 when used with BLV10159 front quick-hitch.</i>	USD \$500.00
6888	2000-rpm front PTO <i>For model year 2017 and newer 2025R Tractors. Includes BLV10681 2000-rpm front PTO.</i>	USD \$408.00
6886	2000-rpm front PTO	USD \$340.00

60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
6885	<i>For model year 2017 and newer 2032R and 2038R Tractors. Includes BLV10633 2000-rpm front PTO.</i> 2000-rpm front PTO	USD \$329.00
6895	<i>For model year 2013-2016 2032R, 2520, 2720, 3033R-3046R, and 3120-3720 Tractors. Includes BLV10475 2000-rpm front PTO.</i> 2000-rpm front PTO	USD \$348.00
6896	<i>For 2210 and 2305 Tractors. Includes LVB25966 2000-rpm front PTO.</i> 2000-rpm front PTO.	USD \$320.00
6897	<i>For model year 2013-2016 2025R, and 2320 Tractors. Includes LVB24900 2000-rpm front PTO.</i> 2000-rpm front PTO	USD \$320.00
6910	<i>For 4100 and 4110 Tractors. Includes BM18695 2000-rpm front PTO.</i> Less 2000-rpm front PTO	In Base Price
ATTACHMENTS FOR FIELD CONVERSION FRONT POWER TAKE-OFF (PTO)		
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BM19576	2000 rpm front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R)	USD \$543.56
BLV10633	2000 RPM Front PTO <i>Includes RIO override for front implements.</i>	USD \$524.70
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i> <i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i>	USD \$587.43



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
BLV10681	See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm 2000 RPM Front PTO For model year 2017- 2025R, and 2026R.	USD \$479.36
BLV10452	Includes shaft to route mid-PTO to the front-PTO. Includes front bearing and support structure. Includes RIO override for front implements. Front PTO bracket (3120-3720, 3033R-3046R)	USD \$302.50
BM25304	2000-rpm front PTO (X400 and 2-wheel drive X700s) BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.	USD \$456.89
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE SHAFT		
BM20836	Broom implement drive shaft (model year 2013-16 2025R/2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$543.56
LVB24956	Implement Drive Shaft for Rotary Brooms (3120-3720, 3033R-3046R)	USD \$205.44
BM25775	Broom implement drive shaft (X400/X500 HDGT and X700s)	USD \$400.19
BLV10800	Implement Drive Shaft for Rotary Brooms (model year 2017-2032R, 2036R, and 2038R)	USD \$359.51
BLV10900	Implement Drive Shaft for Rotary Brooms	USD \$339.19
	For model year 1023E, 1025R, 1026R, and model year 2017- 2025R.	
MISCELLANEOUS		



60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
AM128682	Wafers, polypropylene bristle (pack of 16)	USD \$447.70
AM128683	Wafers, steel bristle (pack of 16)	USD \$773.06
BUC11753	Heavy-duty wheel kit (60-in. Heavy-Duty Rotary Broom) <i>Painted green to align mowing trade dress</i>	USD \$607.76
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB25820	Front Three-Point Hitch/Mid Mount Mower Compatibility Brackets <i>Required for use with BLV10316, BLV10439 and BLV10452 Front Three-Point Hitch with A-Frame (3120-3720 and 3033R-3046R Tractors Only) and AutoConnect Mowers.</i>	USD \$206.80
LVB24810	Front 3-Point Hitch and Mid-Mount Mower Draft Arms <i>Required for use with LVB25878 Front Three-Point Hitch with A-Frame (3033R-3046R and 3120-3720 Tractors Only) and old 7-Iron Mid-Mount Mowers.</i>	USD \$496.49
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit	USD \$84.70

60-in. (152-cm) Heavy-Duty Rotary Broom

Code	Description	List price
	<i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	

**52-in. (132-cm) Quick-Hitch Rotary Broom**

Code	Description	List price
3881M	52-in. (132-cm) Quick-Hitch Rotary Broom 52-in. (132-cm) clearing width straight 48-in. (122-cm) clearing width angled Storage stands 21-in. (533-mm) diameter polypropylene brush Gearbox with 3:1 reduction Heavy-duty no. 50 chain drive Two adjustable rear-mounted caster wheels Brush head height adjustment Three spare driveshaft shear bolts mounted to shell	
	BASE MACHINE <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2210, 2305, 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, and 4110 Tractors.</i> <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>Not compatible with BM17347, 425-455 Quick-Hitch updated for use on X400/X500 HDGT's and X700's with BM20979 front-hitch angling retro-fit kit.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i>	
3881M	52-in. (132-cm) Quick-Hitch Rotary Broom	USD \$4,075.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/Canada	In Base Price
	ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BLV11054	52-in. Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$117.70
BLV11056	60-in. Heavy-Duty Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$119.84
	HITCHES Basic Factory Options FRONT HITCH	
6940	Front quick-hitch <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM26236 front quick-hitch.</i>	USD \$731.00

**52-in. (132-cm) Quick-Hitch Rotary Broom**

Code	Description	List price
6952	Front quick-hitch <i>For 1023E, 1025R and 1026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10796 front attaching support kit.</i>	USD \$1,164.00
6956	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i>	USD \$1,207.00
6957	Front quick-hitch <i>For 1023E and 1025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch, BLV10796 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	USD \$1,363.00
6953	Front quick-hitch <i>For model year 2017 and newer 2025R and 2026R Tractors without a single-point hydraulic connector. Includes BLV10708 front quick-hitch and BLV10680 front attaching support kit.</i>	USD \$1,175.00
6959	Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector. Includes BLV10708 front quick-hitch, BLV10680 front attaching support kit, and two BXX11234 flat-face coupler pairs. One BXX11234 flat-face coupler pair is used on the quick-hitch lift cylinder and one pair on a snow blower chute rotation or quick-hitch angling cylinder.</i>	USD \$1,219.00
6960	Front quick-hitch <i>For model year 2017 and newer 2025R Tractors with a single-point hydraulic connector (SPHC). Includes BLV10708 front quick-hitch,</i>	USD \$1,375.00



52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
	<i>BLV10680 front attaching support kit, and BXX10874 SPHC front hitch compatibility kit. BXX10874 simultaneously connects a quick-hitch's lift and angling cylinders as needed for a front blade or rotary broom. Customers with a snow blower and quick-hitch should order two BXX11234 flat-face coupler pairs as BXX10874 connects to the angling cylinder preventing operation of the chute rotation cylinder.</i>	
6943	Front quick-hitch <i>For 2210 and 2305 Tractors. Includes BM20921 front quick-hitch. Requires LVB25396 front attaching support.</i>	USD \$753.00
6963	Front quick-hitch <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Includes LVB24898 front quick-hitch. Model year 2013-2016 2025R and 2320 Tractors require LVB24895 front attaching support. Model year 2013-2016 2032R, 2520, 2720, 4100, 4110, and 4115 Tractors require LVB25302 front attaching support. 4010 Tractors require LVB25293 front attaching support. LVB25293 must be built from component parts.</i>	USD \$823.00
6967	Less front hitch	In Base Price
	HYDRAULIC ANGLING	
6800	HYDRAULIC ANGLING <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25609 hydraulic angling.</i>	USD \$225.00
6805	Hydraulic angling <i>For 1023E, 1025R, 1026R, model year 2017 and newer 2025R, and 2026R Tractors. Includes BLV10880 hydraulic angling.</i>	USD \$298.00
6802	Hydraulic angling <i>For 2210 and 2305 Tractors. Includes BM20922 hydraulic angling.</i>	USD \$227.00
6803	Hydraulic angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4100, 4010, 4110 and 4115 Tractors. Includes LVB24901 hydraulic angling.</i>	USD \$227.00



52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
6818	Less Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BLV10880	Hydraulic Angling	USD \$349.89
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
ATTACHING COMPONENTS		
Basic Factory Options		
MOUNTING KIT / DRIVESHAFT		
6843	Broom drive shaft <i>For X400/X500 Heavy-Duty Garden and X700 Tractors. Includes BM25775 broom drive shaft.</i>	USD \$341.00
6847	Broom mounting kit and drive shaft <i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017 and newer 2025R Tractors. Includes BLV10900 broom drive shaft and BLV10794 mounting frame.</i>	USD \$320.00
6851	Broom drive shaft <i>For model year 2013-2016 2025R, model year 2013-2016 2032R,</i>	USD \$462.00



52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
6835	2320, 2520, 2720, 4100 and 4110 Tractors. Includes BM20836 broom drive shaft. Less mounting kit and drive shaft	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
MOUNTING FRAME		
BLV10794	52-in. Quick-Hitch Rotary Broom mounting frame For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$37.46
POWER TAKE-OFF		
Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		
6889	2000-rpm front PTO (2-wheel drive) For X400 Heavy-Duty Garden, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754 Tractors. Includes BM25304 2000-rpm front PTO. Must be used with BM25775 broom drive shaft, BM25772 implement drive and upstop, or BUC11685 snow blower upstop and drive shaft.	USD \$399.00
6890	2000-rpm front PTO (4-wheel drive) For X500 Heavy-Duty Garden, X728, X729, X748, X749, X738, X739, and X758 Tractors. Includes BM25305 2000-rpm front PTO.	USD \$399.00
6887	2000-rpm front PTO For 1023E, 1025R, and 1026R Tractors. Includes BLV10786 2000-rpm front PTO. See DTAC solution 111853 when used with BLV10159 front quick-hitch.	USD \$500.00
6888	2000-rpm front PTO For model year 2017 and newer 2025R Tractors. Includes BLV10681 2000-rpm front PTO.	USD \$408.00
6885	2000-rpm front PTO For model year 2013-2016 2032R, 2520, and 2720 Tractors. Includes BLV10475 2000-rpm front PTO.	USD \$329.00
6895	2000-rpm front PTO For 2210 and 2305 Tractors. Includes LVB25966 2000-rpm front PTO.	USD \$348.00
6896	2000-rpm front PTO.	USD \$320.00

52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
6897	<i>For model year 2013-2016 2025R, and 2320 Tractors. Includes LVB24900 2000-rpm front PTO.</i> 2000-rpm front PTO <i>For 4100 and 4110 Tractors. Includes BM18695 2000-rpm front PTO.</i>	USD \$320.00
6910	Less 2000-rpm front PTO	In Base Price
ATTACHMENTS FOR FIELD CONVERSION FRONT POWER TAKE-OFF (PTO)		
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i>	USD \$587.43
BLV10681	<i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> <i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i> 2000 RPM Front PTO <i>For model year 2017- 2025R, and 2026R.</i>	USD \$479.36
BM25304	<i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> 2000-rpm front PTO (X400 and 2-wheel drive X700s)	USD \$456.89



52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
	<i>BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.</i>	
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
	IMPLEMENT DRIVE SHAFT	
BM20836	Broom implement drive shaft (model year 2013-16 2025R/2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$543.56
BM25775	Broom implement drive shaft (X400/X500 HDGT and X700s)	USD \$400.19
BLV10900	Implement Drive Shaft for Rotary Brooms <i>For model year 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$339.19
	MISCELLANEOUS	
	ATTACHMENTS FOR FIELD CONVERSION	
	MISCELLANEOUS	
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
BUC11756	Thatching-wheel kit (52-in. Rotary Broom) <i>Painted green to align mowing trade dress</i>	USD \$620.60
BUC11751	Deflector kit (52-in. Rotary Broom) <i>Painted green to align mowing trade dress</i>	USD \$165.86
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year	USD \$182.60

52-in. (132-cm) Quick-Hitch Rotary Broom

Code	Description	List price
LVB25302	2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i> Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70

**42-in. Accel Deep Mower Deck (42A)**

Code	Description	List price
537LM	42-in. Accel Deep Mower Deck (42A) 42-in. (107-cm) cutting widthSide discharge Accel Deep™12-gauge, 0.105-in. (2.7-mm) stamped-steel deck shellBelt driveTwo greaseable blade spindlesMower wash portTwo front mower wheels	
	BASE MACHINE <i>For Model Year 2016- Select Series Tractors (X330, X350, X354, and X370).</i> <i>Green-painted mower decks align trade dress for all mowing products</i>	
537LM	42-in. Accel Deep Mower Deck (42A)	USD \$885.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/CANANDA	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30

**48-in. Accel Deep Mower Deck (48A)**

Code	Description	List price
537NM	48-in. Accel Deep Mower Deck (48A) 48-in. (122-cm) cutting widthSide discharge Accel Deep™10-gauge, 0.135-in. (3.4-mm) stamped-steel deck shellBelt driveThree greaseable blade spindlesMower wash portFour mower wheels and front center rollerMower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>For Model Year 2016- Select Series Tractors (X330, X350, X354, X370, X380, X384, X390, X394, X570, X580, X584, and X590 Serial 110,001-).</i> <i>X330, X350, and X354 tractors shipped with 42A mower deck or less deck require BM25887 lift assist spring kit.</i> <i>Green-painted mower decks align trade dress for all mowing products</i>	
537NM	48-in. Accel Deep Mower Deck (48A)	USD \$1,450.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/CANANDA	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30

**54-in. Accel Deep Mower Deck (54A)**

Code	Description	List price
537PM	54-in. Accel Deep Mower Deck (54A) 54-in. (137-cm) cutting width Side discharge Accel Deep™ 10-gauge, 0.135-in. (3.4-mm) stamped-steel deck shell Belt drive Three greaseable blade spindles Mower wash port Four mower wheels and front center roller Mower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>For Model Year 2016- Select Series Tractors (X380, X384, X390, X394, X570, X580, X584, and X590 Serial 110,001-).</i> <i>Green-painted mower decks align trade dress for all mowing products</i>	
537PM	54-in. Accel Deep Mower Deck (54A)	USD \$1,900.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	US/CANANDA	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30

**44-in. Front Blade (model year 2006-2015 X300s)**

Code	Description	List price
6008M	44-in. Front Blade (model year 2006-2015 X300s) 1118 mm (44 in.) Cutting Width 1016 mm (40 in.) Cutting Width at 25 degree angle 3 Angling Positions 3.05 mm (0.12 in.) Blade Thickness	
	BASE MACHINE <i>F.O.B. Davenport, Iowa</i>	
6008M	44-in. Front Blade (model year 2006-2015 X300s)	USD \$825.00
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
LP33712	Manual angling kit (44-in. Front Blade X300s)	USD \$209.99
M146542	Front blade rubber squeegee (44-in. blade) <i>Requires 7 03M7188 bolts and 7 14M7273 nuts</i>	USD \$113.21
AM135847	Snow blower and front blade replacement tractor side lift parts <i>Replaces the tractor mounted lift parts from a 2006-2015 44-in. Snow Blower (7001M/SKU23045), 47-in. Snow Blower (7002M/SKU23047), 44-in. Front Blade (6001M/SKU23044), or 48-in. Front Blade (6002M/SKU23048) for use on a model year 2006-2015 X300/X500 M-T tractor.</i>	USD \$430.82

**54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)**

Code	Description	List price
02C1M	54 In. Quick-Hitch Two-Stage Snow Blower (ALDI) Hydraulic Discharge Chute Rotation 100 Degrees Right and Left 54 In. Clearing Width "Straight" 15 In. Diameter Impeller 16 In. Diameter Auger Shear Bolt Protection Adjustable Spout Cap Deflector Two-Stage Design Wear Plates Reversible and Replaceable Scraper Blade Four Extra Shear Bolts "Shell Mounted" Hydraulic Chute Angling Less Front Quick-Hitch Less Front PTO Less Implement Drive and Upstop	
	BASE MACHINE <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2305, 2025R, model year 2013-2016 2032R, 2320-2720 Tractors.</i> <i>See Sales Manual for ballast requirements.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>F.O.B. Davenport, Iowa</i>	
02C1M	54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)	USD \$3,350.00
	HITCHES Basic Factory Options FRONT QUICK-HITCH	
2005	Front Quick-Hitch and Hydraulic Lift <i>For X400-X500 Heavy Duty Garden Tractors, X700s, and X940s.</i>	USD \$645.00
2006	Front Quick-Hitch and Hydraulic Lift <i>For 2305 Tractor.</i> <i>Also requires LVB25396 front attaching support.</i>	USD \$685.00
2007	Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, and</i>	USD \$749.00



54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
2013	2320, 2520, 2720 Tractors. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720). Front Quick-Hitch and Hydraulic Lift For model year 2017- 2025R Tractors.	USD \$959.00
2012	Includes BLV10680 front attaching support kit. Front Quick-Hitch and Hydraulic Lift For 1023E, 1025R, and 1026R.	USD \$950.00
2010	Includes BLV10796 front attaching support kit. Less Front Quick-Hitch	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit Required on X700, X710, X465, X475, and 425 Tractors	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s)	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) Fits also 2210 Tractors (for 47SB only).	USD \$1,112.80
POWER TAKE-OFF		
Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		
3007	2000 RPM Front PTO For 2305 Tractor.	USD \$295.00
3008	2000 RPM Front PTO Kit For model year 2013-2016 2025R and 2320.	USD \$272.00

**54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)**

Code	Description	List price
3017	2000 RPM Front PTO Kit <i>For model year 2017- 2025R.</i>	USD \$371.00
3016	2000 RPM Front PTO Kit <i>For 1023E, 1025R, and 1026R. See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i>	USD \$455.00
3009	2000 RPM Front PTO <i>For model year 2013-2016 2032R, and 2520-2720.</i>	USD \$279.00
3010	Less Power Take Off	In Base Price
3014	2-Wheel Drive 2000 RPM Front PTO <i>For X400 Heavy Duty Garden Tractors, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754. Must be used with BM25772 implement drive and upstop. BM25772 is available as an attachment through parts, BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013.</i>	USD \$351.00
3015	4-Wheel Drive 2000 RPM Front PTO <i>For X500 Heavy Duty Garden Tractors, X728, X729, X748, X749, X738, X739, and X758.</i>	USD \$351.00
IMPLEMENT DRIVE AND UPSTOP		
4005	Implement Drive and Upstop <i>For model year 2013-2016 2025R, 2013-2016 2032R, 2320, 2520, and 2720 tractors.</i>	USD \$386.00
4014	Implement Drive and Upstop <i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017- 2025R. Includes BLV10899 implement drive shaft and BLV10793 upstop.</i>	USD \$441.00
4010	Less Implement Drive and Upstop	In Base Price
4013	Implement Drive and Upstop	USD \$280.00



54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
	<i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i> ATTACHMENTS FOR FIELD CONVERSION FRONT POWER TAKE-OFF (PTO)	
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i> <i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> <i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i>	USD \$587.43
BLV10681	2000 RPM Front PTO <i>For model year 2017- 2025R, and 2026R.</i> <i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i>	USD \$479.36
BM25304	2000-rpm front PTO (X400 and 2-wheel drive X700s) <i>BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and</i>	USD \$456.89



54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
BM25305	60-in. Broom (3790M) option code 5004. 2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE AND UPSTOP		
BLV10793	Snow Blower Attaching Kit (Upstop) <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$220.41
BLV10899	Snow Blower Drive Shaft <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$349.89
MISCELLANEOUS		
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
BM20960	Remote spout cap control kit <i>For 425-455, 318, 322, 332, 420, 430, X400/X500 HDGT's, F900's, X700's, 2210, 2305, 4010, 4100, 4110, 4115 Tractors. See Sales Manual for required attaching parts.</i>	USD \$154.09
LVB24958	Remote Spout Cap Control Kit <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, and 2720 tractors. See Sales Manual for required attaching parts.</i>	USD \$184.04
AM128336	Right-side skid shoe plate and hardware	USD \$70.06
AM128337	Left-side skid shoe plate and hardware	USD \$68.73
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99
BLV10843	Remote Spout Kit <i>Fits 1023E, 1025R, 1026R and 2025R Tractors. Requires BLV10720</i>	USD \$335.99

**54 In. Quick-Hitch Two-Stage Snow Blower (ALDI)**

Code	Description	List price
LVB24895	<i>electric remote spout cap control chassis harness.</i> Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
BXX11138	Remote Spout Control Kit <i>Includes tractor-side harnesses, switch, and hardware to adjust snow blower spout cap from the tractor seat. 1023E and 1025R require BXX10391 junction block kit.</i>	USD \$299.50
LVB26213	Remote Spout Cap Control Kit <i>For 1023E, 1025R, and 1026R open-station Tractors. Not compatible with cab.</i>	USD \$248.24
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70
DESTINATION AND LANGUAGE ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT		
BLV11058	47-in. and 54-in. Quick Hitch Snowblower Spanish kit (CUTs)	USD \$103.79



47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
1474M	47 In. Quick-Hitch Two-Stage Snow Blower (ALDI) Hydraulic Discharge Chute Rotation 100 Degrees Right and Left 47 In. Clearing Width "Straight" 15.5 In. Diameter Impeller 16 In. Diameter Auger Shear Bolt Protection Adjustable Spout Cap Deflector Two-Stage Design Wear Plates Reversible and Replaceable Scraper Blade Four Extra Shear Bolts "Shell Mounted" Hydraulic Chute Angling Less Front Quick-Hitch Less Front PTO Less Implement Drive and Upstop	
	BASE MACHINE <i>BM20761 hydraulic coupler kit required on 425, X465, X475, X700, and X710 Tractors.</i> <i>For 425, 445, 455, X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2210, 2305, 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115 Tractors.</i> <i>See Sales Manual for ballast requirements.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>F.O.B. Davenport, Iowa</i>	
1474M	47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)	USD \$2,800.00
	HITCHES Basic Factory Options FRONT QUICK-HITCH	
2000	Front Quick-Hitch and Hydraulic Lift <i>For 425, 445, and 455.</i>	USD \$667.00
2005	Front Quick-Hitch and Hydraulic Lift <i>For X400-X500 Heavy Duty Garden Tractors, X700s, and X940s.</i>	USD \$645.00
2006	Front Quick-Hitch and Hydraulic Lift <i>For 2210, 2305 Tractors. Also requires LVB25396 front attaching support.</i>	USD \$685.00



47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
2007	Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115).</i>	USD \$749.00
2013	Front Quick-Hitch and Hydraulic Lift <i>For model year 2017- 2025R Tractors.</i>	USD \$959.00
2012	<i>Includes BLV10680 front attaching support kit.</i> Front Quick-Hitch and Hydraulic Lift <i>For 1023E, 1025R, and 1026R.</i>	USD \$950.00
2010	<i>Includes BLV10796 front attaching support kit.</i> Less Front Quick-Hitch	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM20896	Hydraulic retro kit <i>Required to fit a customer's 425, 445 and 455 snow blower or snow thrower on a new X400/X500 HDGT or X700 Series tractor.</i>	USD \$38.51
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s)	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
POWER TAKE-OFF		
Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		

**47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)**

Code	Description	List price
3000	2000 RPM Front PTO <i>For 425, 445, and 455.</i>	USD \$246.00
3003	2000 RPM Front PTO <i>For 4100 and 4110.</i>	USD \$272.00
3006	2000 RPM Front PTO <i>For 4010 and 4115.</i>	USD \$272.00
3007	2000 RPM Front PTO <i>For 2210, 2305 Tractors.</i>	USD \$295.00
3008	2000 RPM Front PTO Kit <i>For model year 2013-2016 2025R and 2320.</i>	USD \$272.00
3017	2000 RPM Front PTO Kit <i>For model year 2017- 2025R.</i>	USD \$371.00
3016	2000 RPM Front PTO Kit <i>For 1023E, 1025R, and 1026R. See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i>	USD \$455.00
3009	2000 RPM Front PTO <i>For model year 2013-2016 2032R, and 2520-2720.</i>	USD \$279.00
3010	Less Power Take Off	In Base Price
3014	2-Wheel Drive 2000 RPM Front PTO <i>For X400 Heavy Duty Garden Tractors, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754. Must be used with BM25772 implement drive and upstop. BM25772 is available as an attachment through parts, BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013.</i>	USD \$351.00
3015	4-Wheel Drive 2000 RPM Front PTO <i>For X500 Heavy Duty Garden Tractors, X728, X729, X748, X749, X738,</i>	USD \$351.00



47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
	<i>X739, and X758.</i>	
	IMPLEMENT DRIVE AND UPSTOP	
4000	Implement Drive and Upstop <i>For 425, 445, and 455.</i>	USD \$231.00
4005	Implement Drive and Upstop <i>For model year 2013-2016 2025R, 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 tractors.</i>	USD \$386.00
4014	Implement Drive and Upstop <i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$441.00
4010	<i>Includes BLV10899 implement drive shaft and BLV10793 upstop.</i> Less Implement Drive and Upstop	In Base Price
4013	Implement Drive and Upstop <i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i>	USD \$280.00
	ATTACHMENTS FOR FIELD CONVERSION	
	FRONT POWER TAKE-OFF (PTO)	
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i>	USD \$587.43
	<i>Includes shaft to route mid-PTO to the front-PTO.</i>	
	<i>Includes front bearing and support structure.</i>	
	<i>Includes RIO override for front implements.</i>	
	<i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom</i>	



47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
BLV10681	(3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm 2000 RPM Front PTO For model year 2017- 2025R, and 2026R. Includes shaft to route mid-PTO to the front-PTO. Includes front bearing and support structure. Includes RIO override for front implements.	USD \$479.36
BM17330	2000-rpm front power take-off (PTO) (415, 425, 445, 455)	USD \$347.76
BM25304	2000-rpm front PTO (X400 and 2-wheel drive X700s) BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.	USD \$456.89
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE AND UPSTOP		
BLV10793	Snow Blower Attaching Kit (Upstop) For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$220.41
BLV10899	Snow Blower Drive Shaft For 1023E, 1025R, 1026R, and model year 2017- 2025R.	USD \$349.89
MISCELLANEOUS		
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
M88984	Drift blade For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.	USD \$44.29
LVB25396	Front Attaching Support Kit (2305) 2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.	USD \$139.10



47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)

Code	Description	List price
BM20960	Remote spout cap control kit <i>For 425-455, 318, 322, 332, 420, 430, X400/X500 HDGT's, F900's, X700's, 2210, 2305, 4010, 4100, 4110, 4115 Tractors. See Sales Manual for required attaching parts.</i>	USD \$154.09
LVB24958	Remote Spout Cap Control Kit <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, and 2720 tractors. See Sales Manual for required attaching parts.</i>	USD \$184.04
AM119321	Heavy-duty skid shoe (1) <i>For 47-in. Quick Hitch Snow Blowers (SN -060,000)</i>	USD \$99.67
AM128336	Right-side skid shoe plate and hardware	USD \$70.06
AM128337	Left-side skid shoe plate and hardware	USD \$68.73
M157831	Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99
BLV10843	Remote Spout Kit <i>Fits 1023E, 1025R, 1026R and 2025R Tractors. Requires BLV10720 electric remote spout cap control chassis harness.</i>	USD \$335.99
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
BXX11138	Remote Spout Control Kit <i>Includes tractor-side harnesses, switch, and hardware to adjust snow blower spout cap from the tractor seat. 1023E and 1025R require BXX10391 junction block kit.</i>	USD \$299.50
LVB26213	Remote Spout Cap Control Kit <i>For 1023E, 1025R, and 1026R open-station Tractors. Not compatible with cab.</i>	USD \$248.24

**47 In. Quick-Hitch Two-Stage Snow Blower (ALDI)**

Code	Description	List price
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70
DESTINATION AND LANGUAGE ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT		
BLV11058	47-in. and 54-in. Quick Hitch Snowblower Spanish kit (CUTs)	USD \$103.79

**54 in. Quick-Hitch Front Blade (ALDI)**

Code	Description	List price
1492M	54 in. Quick-Hitch Front Blade (ALDI) 1372 mm (54 in.) Clearing Width Straight 1219 mm (48 in.) Clearing Width Fully Angled Replaceable Cutting Edge Heavy 11-Gauge, Curved Blade Angled Left or Right Up to 27 degrees Two Adjustable Skid Shoes Reinforced Angle Bar on Back of Blade Spring Breakaway with Lock-Out Pin	
	BASE MACHINE <i>See Sales Manual for ballast requirements.</i> <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>BM20761 hydraulic coupler kit required on 425, X465, X475, X700, and X710 Tractors.</i> <i>For 425, 445, 455, X400/X500 Heavy Duty Garden Tractors, X700s, X940s, X950R, 1023E, 1025R, 1026R, 2210, 2305, 2025R, 2026R, 2027R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110 and 4115 Tractors.</i> <i>F.O.B. Davenport, Iowa</i>	
1492M	54 in. Quick-Hitch Front Blade (ALDI)	USD \$750.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
0202	United States <i>Requires option code 0409 English operator's manual and decal kit or option code 0437 Spanish operator's manual and decal kit.</i>	In Base Price
0184	Canada <i>Requires option code 0409 English operator's manual and decal kit or option code 0413 French operator's manual and decal kit.</i>	No Added Cost
0205	Quebec <i>Requires option code 0413 French operator's manual and decal kit.</i>	No Added Cost
0195	Mexico <i>Requires option code 0457 Spanish operator's manual and no-text</i>	No Added Cost



54 in. Quick-Hitch Front Blade (ALDI)

Code	Description	List price
	<i>decal kit.</i>	
	OPERATOR'S MANUAL	
0409	English operator's manual and decal kit	In Base Price
0413	French Canada operator's manual and decal kit	No Added Cost
0437	Spanish operator's manual and decal kit	No Added Cost
0448	English operator's manual and no-text decal kit	No Added Cost
0457	Spanish operator's manual and no-text decal kit	No Added Cost
	HITCHES	
	Basic Factory Options	
	FRONT QUICK-HITCH	
6940	Front Quick-Hitch and Hydraulic Lift <i>For X400 and X500 Heavy Duty Garden Tractors, X700s, X940s.</i>	USD \$645.00
6947	Front Quick-Hitch and Hydraulic Lift <i>For 425, 445, and 455.</i>	USD \$667.00
6943	Front Quick-Hitch and Hydraulic Lift <i>For 2210 and 2305. Also requires LVB25396 front attaching support.</i>	USD \$685.00
6950	Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115).</i>	USD \$749.00
6953	Front Quick-Hitch and Hydraulic Lift <i>For model year 2017- 2025R, and 2026R.</i>	USD \$959.00
6952	<i>Includes BLV10680 front attaching support kit.</i> Front Quick-Hitch and Hydraulic Lift <i>For 1023E, 1025R, and 1026R.</i>	USD \$950.00
6968	<i>Includes BLV10796 front attaching support kit.</i> Less Front Quick-Hitch	In Base Price
	HYDRAULIC ANGLING	

**54 in. Quick-Hitch Front Blade (ALDI)**

Code	Description	List price
6800	Hydraulic Angling <i>For X400/X500 Heavy Duty Garden Tractors, X700s, X940s, and X950R.</i>	USD \$198.00
6801	Hydraulic Angling <i>For 425, 445, and 455.</i>	USD \$173.00
6802	Hydraulic Angling <i>For 2210 and 2305.</i>	USD \$200.00
6803	Hydraulic Angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$206.00
6805	Hydraulic Angling <i>For 1023E, 1025R, 1026R, model year 2017- 2025R, and 2026R.</i>	USD \$271.00
6818	Less Hydraulic Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM17347	Front quick hitch and hydraulic lift (415, 425, 445, 455)	USD \$1,201.61
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29

**54 in. Quick-Hitch Front Blade (ALDI)**

Code	Description	List price
BM17650	Hydraulic angling (415, 425, 445, 455)	USD \$230.06
BLV10880	Hydraulic Angling	USD \$349.89
MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS		
M42868	Front blade rubber squeegee (48-in. and 54-in. blades) <i>48-in. (122-cm) Front Blade requires 7 03M7188 bolts and 7 14M7273 nuts.</i> <i>54-in. (137-cm) Front Blade requires 10 03M7188 bolts and 10 14M7273 nuts.</i>	USD \$96.63
LP64664	Snow plow markers <i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i>	USD \$39.99
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
AM119321	Heavy-duty skid shoe (1) <i>Optional upgrade on 48-in. (122-cm) Front Blades and 54-in. (137-cm) Quick Hitch Front Blade. Standard equipment on 60-in. (152-cm) Quick Hitch Front Blade. Two required.</i>	USD \$99.67
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60

54 in. Quick-Hitch Front Blade (ALDI)

Code	Description	List price
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
3790M	60 In. Heavy-Duty Rotary Broom (ALDI) 57 In. (1,448 mm) Clearing Width "Straight" 50 In. (1,270 mm) Clearing Width "Angled" Storage Stands 26 In. (660 mm) Diameter Polypropylene Brush Gearbox with 3:1 Reduction Chain and Sprocket Final Drive (2) Adjustable Rear Mounted Caster Wheels Broom Head Float Four Spare Driveshaft Shear Bolts Two Sizes, "Mounted to Shell"	
	BASE MACHINE <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2305, 2025R, 2032R, 2036R, 2038R, 2320, 2520, 2720, 3120-3720, 3033R-3046R, 2210, 4010, 4100, 4110, 4115, and 4400-4410 Tractors.</i> <i>3120-3720 Tractors with mid-mount mowers for use with front three-point hitch with A-Frame require LVB25820 (AutoConnect decks) or LVB24810 (old 7-Iron decks).</i> <i>Small chassis compact tractors also require front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>Compact tractors require dual selective control valve and mid PTO.</i> <i>Not compatible with BM17347, 400-Series Quick-Hitch.</i> <i>See Sales Manual for ballast requirements.</i> <i>F.O.B. Davenport, Iowa</i>	
3790M	60 In. Heavy-Duty Rotary Broom (ALDI)	USD \$4,500.00
	ATTACHING COMPONENTS Basic Factory Options MOUNTING FRAME	
1000	Mounting Frame <i>For X400/X500 Heavy Duty Garden Tractors, X700s, 2210, 2305, 2320, 2520, 2720, 4010, 4100, 4110, 4115, model year 2013-2016 2025R, and model year 2013-2016 2032R.</i>	USD \$411.00
1004	Mounting Frame <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$411.00

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
1002	Mounting Frame with Drive Shaft and Hydraulic Angling <i>For 3033R-3046R, and 3120-3720.</i>	USD \$847.00
1003	Mounting Frame with Drive Shaft and Hydraulic Angling <i>For model year 2017- 2032R, 2036R and 2038R.</i>	USD \$892.00
1010	Less Mounting Frame	In Base Price
ATTACHMENTS FOR FIELD CONVERSION MOUNTING FRAME		
BM20626	60-in. Rotary Broom mounting frame <i>For use on X400/X500 HDGT's, X700s, 2210, 2305, model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$545.70
BLV10776	Mounting Frame and Hydraulic Angling (3120-3720, 3033R-3046R, model year 2017- 2032R, 2036R, and 2038R)	USD \$1,070.00
BLV10795	60-in. Rotary Broom mounting frame <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$666.61
HITCHES Basic Factory Options FRONT QUICK-HITCH		
2000	Front Quick-Hitch and Hydraulic Lift <i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i>	USD \$645.00
2004	Front Quick-Hitch and Hydraulic Lift <i>For 2210 and 2305.</i>	USD \$685.00
2005	<i>Also requires LVB25396 front attaching support.</i> Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115).</i>	USD \$749.00
2012	Front Quick-Hitch and Hydraulic Lift <i>For model year 2017- 2025R Tractors.</i>	USD \$959.00



60 In. Heavy-Duty Rotary Broom (ALDI)

Code	Description	List price
2011	<i>Includes BLV10680 front attaching support kit.</i> Front Quick-Hitch and Hydraulic Lift <i>For 1023E, 1025R, and 1026R.</i>	USD \$950.00
2008	<i>Includes BLV10796 front attaching support kit.</i> Front Three-Point Hitch with A-Frame Quick Attach System <i>For 3120-3720, and 3033R-3046R.</i>	USD \$1,488.00
2009	Front Three-Point Hitch with A-Frame Quick Attach System <i>For model year 2017- 2032R, 2036R and 2038R.</i>	USD \$1,476.00
2010	Less Front Quick-Hitch and Hydraulic Lift	In Base Price
HYDRAULIC ANGLING		
	<i>Hydraulic Angling for 3120-3720, model year 2017- 2032R, 2036R, 2038R, 4200-4400, and 4210-4410 Tractors are included in option codes 1001, 1002, and 1003.</i>	
3000	Hydraulic Angling <i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i>	USD \$198.00
3002	Hydraulic Angling Kit <i>For 2210 and 2305.</i>	USD \$200.00
3003	Hydraulic Angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$206.00
3005	Hydraulic Angling <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$271.00
3010	Less Hydraulic Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BLV10634	Auxiliary Front Hydraulic Coupler Kit <i>Includes couplers, hoses, and brackets to route hydraulics from the mid-SCV to the front three-point hitch.</i>	USD \$371.80
BLV10638	Hydraulic accumulator kit for front 3-point hitch <i>For use in applications where there is significant transporting done at higher speeds. Accumulator system will absorb the bounce</i>	USD \$433.40

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
	<i>associated with front implements when traveling on the roadway.</i>	
BLV10637	A-frame quick-attach system Category 1N	USD \$377.30
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BLV10439	Front 3-point hitch (3033R-3046R) <i>Requires BLV10452 (Front PTO Bracket).</i>	USD \$1,836.00
BM20921	Front Quick-Hitch and Hydraulic Lift (2305)	USD \$1,112.80
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BLV10880	Hydraulic Angling	USD \$349.89
POWER TAKE-OFF		
Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		
4002	2000 RPM Front PTO Kit <i>For 4100 and 4110.</i>	USD \$272.00
4003	2000 RPM Front PTO Kit <i>For 4010 and 4115.</i>	USD \$272.00
4004	2000 RPM Front PTO Kit <i>For 4200-4400 and 4210-4410.</i>	USD \$271.00
4005	2000 RPM Front PTO Kit <i>For 2210 and 2305.</i>	USD \$295.00
4006	2000 RPM Front PTO Kit	USD \$272.00

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
	<i>For model year 2013-2016 2025R and 2320.</i>	
4017	2000 RPM Front PTO Kit <i>For model year 2017- 2025R.</i>	USD \$371.00
4007	2000 RPM Front PTO Kit <i>For model year 2013-2016 2032R, 2520, 2720, 3033R-3046R, and 3120-3720.</i>	USD \$279.00
4016	2000 RPM Front PTO Kit <i>For 1023E, 1025R, and 1026R. See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i>	USD \$455.00
4010	Less 2000 RPM Front PTO Kit	In Base Price
4014	2-Wheel Drive 2000 RPM Front PTO <i>For X400 Heavy Duty Garden Tractors, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754. Must be used with BM25775 implement drive shaft for rotary brooms. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.</i>	USD \$351.00
4015	4-Wheel Drive 2000 RPM Front PTO <i>For X500 Heavy Duty Garden Tractors, X728, X729, X748, X749, X738, X739, and X758.</i>	USD \$351.00
4012	2000 RPM Front PTO Kit <i>For model year 2017- 2032R, 2036R and 2038R.</i>	USD \$280.00
IMPLEMENT DRIVE SHAFT		
	<i>Drive Shaft for Model Year 2017- 2032R, 2036R, 2038R, 3120-3720, 4200-4400 and 4210-4410 Tractors are Included in Option Codes 1001, 1002, and 1003.</i>	
5001	Implement Drive Shaft <i>For model year 2013-2016 2025R and 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$275.00
5005	Implement Drive Shaft	USD \$262.00



60 In. Heavy-Duty Rotary Broom (ALDI)

Code	Description	List price
5004	<i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017- 2025R</i> Implement Drive Shaft <i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i>	USD \$262.00
5010	Less Implement Drive Shaft	In Base Price
ATTACHMENTS FOR FIELD CONVERSION FRONT POWER TAKE-OFF (PTO)		
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BM19576	2000 rpm front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R)	USD \$543.56
BLV10633	2000 RPM Front PTO <i>Includes RIO override for front implements.</i>	USD \$524.70
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i> <i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> <i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i>	USD \$587.43
BLV10681	2000 RPM Front PTO <i>For model year 2017- 2025R, and 2026R.</i> <i>Includes shaft to route mid-PTO to the front-PTO.</i>	USD \$479.36

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
	<i>Includes front bearing and support structure.</i>	
	<i>Includes RIO override for front implements.</i>	
BLV10452	Front PTO bracket (3120-3720, 3033R-3046R)	USD \$302.50
BM25304	2000-rpm front PTO (X400 and 2-wheel drive X700s) <i>BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.</i>	USD \$456.89
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE SHAFT		
BM20836	Broom implement drive shaft (model year 2013-16 2025R/2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$543.56
LVB24956	Implement Drive Shaft for Rotary Brooms (3120-3720, 3033R-3046R)	USD \$205.44
BM25775	Broom implement drive shaft (X400/X500 HDGT and X700s)	USD \$400.19
BLV10800	Implement Drive Shaft for Rotary Brooms (model year 2017-2032R, 2036R, and 2038R)	USD \$359.51
BLV10900	Implement Drive Shaft for Rotary Brooms <i>For model year 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$339.19
MISCELLANEOUS		
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
LVB25396	Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
AM128682	Wafers, polypropylene bristle (pack of 16)	USD \$447.70
AM128683	Wafers, steel bristle (pack of 16)	USD \$773.06
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320)	USD \$104.86

**60 In. Heavy-Duty Rotary Broom (ALDI)**

Code	Description	List price
	<i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB25820	Front Three-Point Hitch/Mid Mount Mower Compatibility Brackets <i>Required for use with BLV10316, BLV10439 and BLV10452 Front Three-Point Hitch with A-Frame (3120-3720 and 3033R-3046R Tractors Only) and AutoConenct Mowers.</i>	USD \$206.80
LVB24810	Front 3-Point Hitch and Mid-Mount Mower Draft Arms <i>Required for use with LVB25878 Front Three-Point Hitch with A-Frame (3033R-3046R and 3120-3720 Tractors Only) and old 7-Iron Mid-Mount Mowers.</i>	USD \$496.49
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70
	DESTINATION AND LANGUAGE ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT	
BLV11054	52-in. Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$117.70
BLV11056	60-in. Heavy-Duty Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$119.84

**52 in. Quick-Hitch Rotary Broom (ALDI)**

Code	Description	List price
3880M	52 in. Quick-Hitch Rotary Broom (ALDI) 52 In. (1,321 mm) Clearing Width "Straight" 48 In. (1,219 mm) Clearing Width "Angled" Storage Stands 21 In. (533 mm) Diameter Polypropylene Brush Gearbox with 3:1 Reduction Heavy Duty No. 50 Chain Drive (2) Adjustable Rear Mounting Caster Wheels Brush Head Height Adjustment Three Spare Driveshaft Shear Bolts "Mounted to Shell"	
	BASE MACHINE <i>Compact tractors require dual selective control valve and front attaching support kit. See Sales Manual for front attaching support requirements.</i> <i>Not compatible with BM17347, 425-455 Quick-Hitch updated for use on X400/X500 HDGT's and X700's with BM20979 front-hitch angling retro-fit kit.</i> <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>For X400/X500 Heavy Duty Garden Tractors, X700's, 1023E, 1025R, 1026R, 2210, 2305, 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115 Tractors.</i> <i>F.O.B. Davenport, Iowa</i>	
3880M	52 in. Quick-Hitch Rotary Broom (ALDI)	USD \$3,900.00
	HITCHES Basic Factory Options FRONT QUICK-HITCH	
1000	Front Quick-Hitch and Hydraulic Lift <i>For X400/X500 Heavy Duty Garden Tractors, X700s, and X940s.</i>	USD \$645.00
1012	Front Quick-Hitch and Hydraulic Lift <i>For 1023E, 1025R, and 1026R.</i>	USD \$950.00
1005	<i>Includes BLV10796 front attaching support kit.</i> Front Quick-Hitch and Hydraulic Lift <i>For 2210 and 2305. Also requires LVB25396 front attaching support.</i>	USD \$685.00



52 in. Quick-Hitch Rotary Broom (ALDI)

Code	Description	List price
1006	Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115).</i>	USD \$749.00
1013	Front Quick-Hitch and Hydraulic Lift <i>For model year 2017- 2025R Tractors.</i>	USD \$959.00
	<i>Includes BLV10680 front attaching support kit.</i>	
1010	Less Front Quick-Hitch	In Base Price
HYDRAULIC ANGLING		
2000	Hydraulic Angling <i>For X400/X500 Heavy Duty Garden Tractors, X700s, X940s, and X950R.</i>	USD \$198.00
2006	Hydraulic Angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$206.00
2009	Hydraulic Angling <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$271.00
2005	Hydraulic Angling <i>For 2210 and 2305.</i>	USD \$200.00
2010	Less Hydraulic Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s)	USD \$859.21



52 in. Quick-Hitch Rotary Broom (ALDI)

Code	Description	List price
BM20921	<i>BM25609 hydraulic angling kit recommended</i> Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BLV10880	Hydraulic Angling	USD \$349.89
POWER TAKE-OFF		
Basic Factory Options		
FRONT POWER TAKE-OFF (PTO)		
3003	2000 RPM Front PTO <i>For 4100 and 4110.</i>	USD \$272.00
3004	2000 RPM Front PTO <i>For 4010 and 4115.</i>	USD \$272.00
3005	2000 RPM Front PTO <i>For 2210 and 2305.</i>	USD \$295.00
3006	2000 RPM Front PTO <i>For model year 2013-2016 2025R and 2320.</i>	USD \$272.00
3017	2000 RPM Front PTO Kit <i>For model year 2017- 2025R.</i>	USD \$371.00
3007	2000 RPM Front PTO <i>For model year 2013-2016 2032R, 2520, and 2720.</i>	USD \$279.00
3016	2000 RPM Front PTO Kit <i>For 1023E, 1025R, and 1026R. See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007.</i> http://dtac.deere.com/Solutions/English/111853.htm	USD \$455.00



52 in. Quick-Hitch Rotary Broom (ALDI)

Code	Description	List price
3010	Less 2000 RPM Front PTO	In Base Price
3014	2-Wheel Drive 2000 RPM Front PTO <i>For X400 Heavy Duty Garden Tractors, X700, X720, X724, X740, X744, X710, X730, X734, X750, and X754. Must be used with BM25775 implement drive shaft for rotary brooms. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.</i>	USD \$351.00
3015	4-Wheel Drive 2000 RPM Front PTO <i>For X500 Heavy Duty Garden Tractors, X728, X729, X748, X749, X738, X739, and X758.</i>	USD \$351.00
IMPLEMENT DRIVE SHAFT		
4006	Implement Drive Shaft <i>For 2210, 2305, 1023E, 1025R, 1026R, and model year 2017- 2025R.</i> <i>Includes BLV10900 implement drive shaft and BLV10794 mounting frame.</i>	USD \$291.00
4002	Implement Drive Shaft <i>For model year 2013-2016 2025R and 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115 Tractors.</i>	USD \$275.00
4004	Implement Drive Shaft <i>For X400/X500 Heavy Duty Garden Tractors and X700's.</i>	USD \$262.00
4010	Less Implement Drive Shaft	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT POWER TAKE-OFF (PTO)		
BLV10475	2000 RPM Front PTO (model year 2013-2016 2032R, 2520, 2720, 3120-3720, 3033R-3046R) <i>Includes RIO override for front implements.</i>	USD \$506.11
BM18695	2000-rpm Front Power Take-Off (PTO) (4100, 4110)	USD \$350.96
LVB24900	2000-rpm Front Power Take-Off (PTO) (model year 2013-2016 2025R and 2320.	USD \$350.96
LVB25966	2000-rpm Front Power Take-Off (PTO) (2210, 2305)	USD \$516.81
BLV10786	2000 RPM Front PTO <i>For 1023E, 1025R, and 1026R.</i>	USD \$587.43



52 in. Quick-Hitch Rotary Broom (ALDI)

Code	Description	List price
BLV10681	<i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> <i>See DTAC solution 111853 when used with BLV10159 Front Quick-Hitch. BLV10159 Front Quick-Hitch was available as an attachment through parts, 47-in. Snow Blower (1474M) option code 2008, 54-in. Snow Blower (02C1M) option code 2008, 52-in. Rotary Broom (3880M) option code 1001, and 60-in. Broom (3790M) option code 2007. http://dtac.deere.com/Solutions/English/111853.htm</i> 2000 RPM Front PTO <i>For model year 2017- 2025R, and 2026R.</i>	USD \$479.36
BM25304	<i>Includes shaft to route mid-PTO to the front-PTO.</i> <i>Includes front bearing and support structure.</i> <i>Includes RIO override for front implements.</i> 2000-rpm front PTO (X400 and 2-wheel drive X700s) <i>BM25304 must be used with BM25772 implement drive and upstop for snow blowers, or BM25775 implement drive shaft for rotary brooms. BM25772 is available as an attachment through parts, 47-in. Snow Blower (1474M) option code 4013, and 54-in. Snow Blower (02C1M) option code 4013. BM25775 is available as an attachment through parts, 52-in. Rotary Broom (3880M) option code 4004, and 60-in. Broom (3790M) option code 5004.</i>	USD \$456.89
BM25305	2000-rpm front PTO (X500 HDGT and 4-wheel drive X700s)	USD \$456.89
IMPLEMENT DRIVE SHAFT		
BM20836	Broom implement drive shaft (model year 2013-16 2025R/2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$543.56
BM25775	Broom implement drive shaft (X400/X500 HDGT and X700s)	USD \$400.19
BLV10900	Implement Drive Shaft for Rotary Brooms	USD \$339.19
	<i>For model year 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	
MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS		
LVB25396	Front Attaching Support Kit (2305)	USD \$139.10

**52 in. Quick-Hitch Rotary Broom (ALDI)**

Code	Description	List price
LVB24895	<i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i> Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70
DESTINATION AND LANGUAGE ATTACHMENTS FOR FIELD CONVERSION SPANISH NORTH AMERICAN KIT		
BLV11054	52-in. Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$117.70
BLV11056	60-in. Heavy-Duty Quick Hitch Rotary Broom Spanish kit (CUTs)	USD \$119.84
ATTACHING COMPONENTS ATTACHMENTS FOR FIELD CONVERSION MOUNTING FRAME		
BLV10794	52-in. Quick-Hitch Rotary Broom mounting frame <i>For 1023E, 1025R, 1026R, and model year 2017- 2025R.</i>	USD \$37.46

**48-in. Front Blade (model year 2006-2015 X500s) (ALDI)**

Code	Description	List price
6002M	48-in. Front Blade (model year 2006-2015 X500s) (ALDI) 1219 mm (48 in.) Cutting Width 1194 mm (47 in.) Cutting Width at 15 degree angle 1067 mm (42 in.) Cutting Width at 30 degree angle 5 Angling Positions Spring-Trip with Lock 3.05 mm (0.12 in.) Blade Thickness	
	BASE MACHINE <i>For Model Year 2006-2015 Select Series X500 M-T Tractors</i> <i>Rear weights and tire chains are recommended for additional traction.</i> <i>F.O.B. Davenport, Iowa</i>	
6002M	48-in. Front Blade (model year 2006-2015 X500s) (ALDI)	USD \$1,075.00
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
M42868	Front blade rubber squeegee (48-in. and 54-in. blades) <i>48-in. (122-cm) Front Blade requires 7 03M7188 bolts and 7 14M7273 nuts.</i> <i>54-in. (137-cm) Front Blade requires 10 03M7188 bolts and 10 14M7273 nuts.</i>	USD \$96.63
AM135847	Snow blower and front blade replacement tractor side lift parts <i>Replaces the tractor mounted lift parts from a 2006-2015 44-in. Snow Blower (7001M/SKU23045), 47-in. Snow Blower (7002M/SKU23047), 44-in. Front Blade (6001M/SKU23044), or 48-in. Front Blade (6002M/SKU23048) for use on a model year 2006-2015 X300/X500 M-T tractor.</i>	USD \$430.82
LP64664	Snow plow markers <i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i>	USD \$39.99
AM119321	Heavy-duty skid shoe (1) <i>Optional upgrade on 48-in. (122-cm) Front Blades and 54-in. (137-</i>	USD \$99.67

**48-in. Front Blade (model year 2006-2015 X500s) (ALDI)**

Code	Description	List price
	<i>cm) Quick Hitch Front Blade. Standard equipment on 60-in. (152-cm) Quick Hitch Front Blade. Two required.</i>	
BM23448	Manual angling kit (48-in. Front Blade X394 and X500 M-T)	USD \$310.30

**47-in. Snow Blower (X530, X534, X540, model year 2015 X590) (ALDI)**

Code	Description	List price
7002M	47-in. Snow Blower (X530, X534, X540, model year 2015 X590) (ALDI) 1194 mm (47 in.) Clearing Width Easy-On, Easy-Off Mounting 406 mm (16 in.) Diameter Auger Reversible and Replaceable Cutting Blade 200 degree Spout Rotation Cast Iron Gear Box Sealed, Anti-Friction Ball Bearings Remote Spout Cap Control Adjustable Skid Shoes	
	BASE MACHINE <i>For model year 2006-2015 Select Series tractors (X530, X534, X540, and model year 2015 X590).Rear weights and tire chains are recommended for additional traction.Winter grill cover recommended on model year 2006-2013 air-cooled engines to prevent carburetor icing.Also order M158756 spring and M174506 belt when used on model year 2015 X590 (serial 100,001-110,000).Not for sale in France. F.O.B. Davenport, Iowa</i>	
7002M	47-in. Snow Blower (X530, X534, X540, model year 2015 X590) (ALDI)	USD \$2,300.00
	MISCELLANEOUS ATTACHMENTS FOR FIELD CONVERSION MISCELLANEOUS	
AM122263	Skid shoe, heavy-duty left-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$92.27
AM122264	Skid shoe, heavy-duty right-hand (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers</i>	USD \$95.92
M88984	Drift blade <i>For snow blowers. Requires two 19H1914 bolts and two N10217 lock nuts.</i>	USD \$44.29
AM135847	Snow blower and front blade replacement tractor side lift parts <i>Replaces the tractor mounted lift parts from a 2006-2015 44-in. Snow Blower (7001M/SKU23045), 47-in. Snow Blower (7002M/SKU23047), 44-in. Front Blade (6001M/SKU23044), or 48-in.</i>	USD \$430.82

**47-in. Snow Blower (X530, X534, X540, model year 2015 X590) (ALDI)**

Code	Description	List price
M157831	<i>Front Blade (6002M/SKU23048) for use on a model year 2006-2015 X300/X500 M-T tractor.</i> Skid shoe, plastic (1) <i>Used on 44-in. (112-cm) and 47-in. (119-cm) Snow Blowers. Two required.</i>	USD \$47.57
LP70692	Snow blower storage dollies	USD \$159.99

**60-in. Shaft Drive 7-Iron Mower Deck (60D) (ALDI)**

Code	Description	List price
9076M	60-in. Shaft Drive 7-Iron Mower Deck (60D) (ALDI) 60-in. (152-cm) cutting width Side discharge 7-Iron™ 7-gauge, 0.179-in. (4.6-mm) stamped-steel deck shell Shaft drive Three greaseable blade spindles Mower wash port Four mower wheels and front center roller Mower wheels rotate 90 degrees for easy mower removal	
	BASE MACHINE <i>Compatible With Model Year 2007-2012 (Serial 020,001-080,000) X700-Series 2-Wheel Steer Tractors. Not Compatible with 4-Wheel Steer Models.</i> <i>Requires Turf Tires or BM22425 HDAP Tires. BM22425 Tires are Factory Equipment on Serial M0X728A020102- and M0X748A020388-.</i> <i>See Sales Manual for Complete Compatibility Information for 3-Point Hitches, Cabs, Special Edition Models and Special Edition Serial Number Breaks.</i> <i>F.O.B. Horicon, Wisconsin</i>	
9076M	60-in. Shaft Drive 7-Iron Mower Deck (60D) (ALDI)	USD \$3,025.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
001A	United States and Canada	In Base Price
	MOWER DECK ATTACHMENTS FOR FIELD CONVERSION MOWER DECKS	
AM130907	Mower deck leveling gauge	USD \$8.30
	MULCH KITS	
TCB10953	Mulch Kit (1524-mm (60-in.) 7Iron, 7Iron II and 7Iron PRO)	USD \$268.57

**60 in. Quick-Hitch Front Blade (ALDI)**

Code	Description	List price
9820M	60 in. Quick-Hitch Front Blade (ALDI) 1524 mm (60 in.) Clearing Width Straight 1358 mm (53.5 in.) Clearing Width Fully Angled Replaceable Cutting Edge Heavy 7-Gauge, Curved Blade Angled Left or Right Up to 27 degrees Two Adjustable Heavy Duty Skid Shoes Reinforced Angle Bar on Back of Blade Spring Breakaway with Lock-Out Pin	
	BASE MACHINE <i>See Sales Manual for ballast requirements.</i> <i>Compact tractors require dual selective control valve and front attaching support lit. See Sales Manual for front attaching support requirements.</i> <i>BM20761 hydraulic coupler kit required on X465, X475, X700, and X710 Tractors.</i> <i>For X400/X500 Heavy Duty Garden Tractors, X700s, X940s, X950R, 1023E, 1025R, 1026R, 2210, 2305, 2025R, 2026R, 2027R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110 and 4115 Tractors.</i> <i>F.O.B. Davenport, Iowa</i>	
9820M	60 in. Quick-Hitch Front Blade (ALDI)	USD \$1,250.00
	DESTINATION AND LANGUAGE Basic Factory Options DESTINATION	
0202	United States <i>Requires option code 0409 English operator's manual and decal kit or option code 0437 Spanish operator's manual and decal kit.</i>	In Base Price
0184	Canada <i>Requires option code 0409 English operator's manual and decal kit or option code 0413 French operator's manual and decal kit.</i>	No Added Cost
0205	Quebec <i>Requires option code 0413 French operator's manual and decal kit.</i>	No Added Cost
0195	Mexico <i>Requires option code 0457 Spanish operator's manual and no-text</i>	No Added Cost



60 in. Quick-Hitch Front Blade (ALDI)

Code	Description	List price
	<i>decal kit.</i>	
	OPERATOR'S MANUAL	
0409	English operator's manual and decal kit	In Base Price
0413	French Canada operator's manual and decal kit	No Added Cost
0437	Spanish operator's manual and decal kit	No Added Cost
0448	English operator's manual and no-text decal kit	No Added Cost
0457	Spanish operator's manual and no-text decal kit	No Added Cost
	HITCHES	
	Basic Factory Options	
	FRONT QUICK-HITCH	
6940	Front Quick-Hitch and Hydraulic Lift <i>For X400 and X500 Heavy Duty Garden Tractors, X700s, X940s.</i>	USD \$645.00
6943	Front Quick-Hitch and Hydraulic Lift <i>For 2210 and 2305. Also requires LVB25396 front attaching support.</i>	USD \$685.00
6950	Front Quick-Hitch and Hydraulic Lift <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115. Also requires LVB24895 front attaching support (model year 2013-2016 2025R and 2320). Also requires LVB25302 front attaching support (model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115).</i>	USD \$749.00
6953	Front Quick-Hitch and Hydraulic Lift <i>For model year 2017- 2025R, and 2026R.</i>	USD \$959.00
	<i>Includes BLV10680 front attaching support kit.</i>	
6952	Front Quick-Hitch and Hydraulic Lift <i>For 1023E, 1025R, and 1026R.</i>	USD \$950.00
	<i>Includes BLV10796 front attaching support kit.</i>	
6968	Less Front Quick-Hitch	In Base Price
	HYDRAULIC ANGLING	
6800	Hydraulic Angling <i>For X400/X500 Heavy Duty Garden Tractors, X700s, X940s, and</i>	USD \$198.00



60 in. Quick-Hitch Front Blade (ALDI)

Code	Description	List price
6802	X950R. Hydraulic Angling <i>For 2210 and 2305.</i>	USD \$200.00
6803	Hydraulic Angling <i>For model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, and 4115.</i>	USD \$206.00
6805	Hydraulic Angling <i>For 1023E, 1025R, 1026R, model year 2017- 2025R, and 2026R.</i>	USD \$271.00
6818	Less Hydraulic Angling	In Base Price
ATTACHMENTS FOR FIELD CONVERSION		
FRONT QUICK-HITCH		
BLV10708	Quick Hitch Kit	USD \$992.20
BM20761	Hydraulic coupler kit <i>Required on X700, X710, X465, X475, and 425 Tractors</i>	USD \$81.31
LVB24898	Front Quick-Hitch and Hydraulic Lift (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720) <i>Fits also 4010, 4100, 4110 and 4115 Tractors for 47SB only.</i>	USD \$1,216.59
BM26236	Front quick hitch and hydraulic lift (X400/X500 HDGTs, X700s, X940s) <i>BM25609 hydraulic angling kit recommended</i>	USD \$859.21
BM20921	Front Quick-Hitch and Hydraulic Lift (2305) <i>Fits also 2210 Tractors (for 47SB only).</i>	USD \$1,112.80
HYDRAULIC ANGLING		
BM20922	Hydraulic angling (2210, 2305)	USD \$266.43
BM25609	Hydraulic angling (X400/X500 HDGTs, X700s, X940s)	USD \$264.29
LVB24901	Hydraulic angling (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320, 2520, 2720, 4010, 4100, 4110, 4115)	USD \$325.29
BLV10880	Hydraulic Angling	USD \$349.89
MISCELLANEOUS		
ATTACHMENTS FOR FIELD CONVERSION		
MISCELLANEOUS		
LP64664	Snow plow markers	USD \$39.99

**60 in. Quick-Hitch Front Blade (ALDI)**

Code	Description	List price
LVB25396	<i>Compatible with 48-in. Front Blade and 54-in. Quick Hitch Front Blade</i> Front Attaching Support Kit (2305) <i>2210 and 2305 Tractors with 200X or 200CX hood guard require attaching support kit. Fits also 2210 Tractors (for 47SB only.) See Sales Manual for front attaching support requirements.</i>	USD \$139.10
AM119321	Heavy-duty skid shoe (1)	USD \$99.67
LVB24895	Front Attaching Support Kit (model year 2013-2016 2025R, 2320) <i>2025R and 2320 tractors with 200X or 200CX hood guard require attaching support kit. See sales manual for front attaching support requirements.</i>	USD \$104.86
BLV10680	Front Quick Hitch to Tractor Interface Kit	USD \$404.80
BLV10796	Front Attaching Support Kit (Quick Hitch)	USD \$342.10
LVB24899	Front Hitch/Mid-Mount Mower Combo Bracket (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720) <i>Compatible with 4115 Tractor also. Required for Tool Free Change Between 54D or 62D OnRamp Mid-Mount Mower and Quik-Tatch Front Hitch (model year 2013-2016 2025R, model year 2013-2016 2032R, 2320-2720)</i>	USD \$182.60
LVB25302	Front-Attaching Support Kit <i>For model year 2013-2016 2032R, 2520, 2720, 4100, 4110, 4115 tractors. If tractor is equipped with hood guard, attaching support kit is not required. See Sales Manual for front attaching support requirements.</i>	USD \$84.70